

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24090265/Avp3e2	
	(BUDGET DIRECT I	NSURANCE)	Date:	11/11/2024	
	190 CLEMENCEAU SINGAPORE SHOP	AVENUE #03-01 PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFK 200K	Veh. Inspected	SMJ 7010T	
	Policy No.	-	Coverage	0	
	Claim No.	C10031646/MC	Excess	\$0.00	
	Assign From	LAU BOON CHIN	Assign Date	16/09/2024	
2.	2. Vehicle Details				
	Make & Model	TOYOTA PREMIO	C.C	1496	
	Engine No.	1NZD293736	Year of Reg.	14/04/2009	
	Chassis No.	NZT2603038056	Colour	BRONZE	
	Odometer	- KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55 R16	PIRELLI	6	
	L/H Front Tyre	205/55 R16	PIRELLI	6	
	R/H Rear Tyre	205/55 R16	PIRELLI	6	
	L/H Rear Tyre	205/55 R16	PIRELLI	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	11/09/2024	Inspection Date	13/09/2024	
	Survey held at HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair