



ESTABLISHED 1984

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD  
75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557  
ATTN: EILEEN

Ref: CS/INC24090266/Avh3e2(N)  
Date: 05/02/2025  
Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJV 2879J	<b>Veh. Inspected</b>	SMK 4718A
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1294758-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	EILEEN	<b>Assign Date</b>	13/09/2024

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ C200	<b>c.c</b>	1796
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	WDD2040482A474713	<b>Colour</b>	BRONZE
<b>Odometer</b>	135557 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45 R17	MICHELIN	6 mm
<b>L/H Front Tyre</b>	225/45 R17	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	225/45 R17	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	225/45 R17	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	11/09/2024	<b>Inspect Date / Time</b>	16/09/2024 ( 04:14 PM )
<b>Survey held at</b>	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**