

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI24090274/TQH3M4**Date:** 03/10/2024REFERENCE

Insured/Claimant: EVOLUTION AUTOMOBILE PTE.LTD Policy No: DMHCSNA00010702401
 Date of Loss: 09/09/2024 Nature of Claim: OD Claim No: SNM24D205169/C01/SNP1956K/TANC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNP1956K**
 Make & Model: INFINITI Q30, 1.5 D PREMIUM DCT (A) Engine No: K9KG481D002978
 Reg. Date: 20/04/2017 (Man. Year: 2016) Chassis No: SJKDAAH15U1026009
 Colour: Black Odometer: 0 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: S\$42,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	2,000.00	-2,000.00	
Nett Amount (S\$)	0.00	-2,000.00	2,000.00	

INSPECTION

Date of Assignment: 16/09/2024
 Date Inspected: 17/09/2024 Inspected At: AUTOMOTIVE REPAIR CENTRE PTE LTD
 ENTERPRISE HUB 48 TOH GUAN ROAD EAST
 #02-146/147, SINGAPORE 608586
 Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$42,000.00
OMV :	\$30,188.00
PARF Rebate (1) :	\$14,558.00
Quota Premium Paid :	\$50,789.00
COE Rebate (2) :	\$13,134.00
Total Rebate (1) + (2) = :	\$27,692.00

The total amount incurred will be Market Value \$42,000.00 minus Total Rebate \$27,692.00 = \$14,308.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Oct 2024)	
Parts:	N/A	INFINITI Q30 1.5 D PREMIUM DCT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNP1956K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >