

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 18 Sep 2024

Preliminary Advice

Vehicle No	: SNP1956K	Accident Date	: 09/09/2024
Make	: INFINITI Q30	Policy No.	: DMHCSNA00010702401
Assignment Date	: 16/09/2024	Excess	: S\$2,000.00
Date of Inspection	: 17/09/2024	Est. Duration of Repair	: 0
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	60,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	27,692.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,308.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :