

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	S INCOME INSURANCE LTD		Ref:	CS/INC24090279/Unh3
	75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	04/10/2024
	WOOME GENTILE		Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGP 8002A	Veh. Inspected	SMH 3892B
	Policy No.	-	Coverage	0
	Claim No.	MT/1294855-002	Excess	\$0.00
	Assign From	RAJESWARY	Assign Date	17/09/2024
2. Vehicle Details				
	Make & Model	HONDA CIVIC 1.5 (A)	C.C	1498
	Engine No.	L15B73625185	Year of Reg.	21/01/2019
	Chassis No.	MRHFC1660JT000292	Colour	BLACK
	Odometer	274618 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	215/50R17	MICHELIN	6
	L/H Front Tyre	215/50R17	MICHELIN	6
	R/H Rear Tyre	215/50R17	MICHELIN	6
	L/H Rear Tyre	215/50R17	MICHELIN	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	11/09/2024	Inspection Date	17/09/2024 (12:33)
	Survey held at	T K LEE AUTOMOTIVE PTE LTD		
		NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY		
		SINGAPORE 417883		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				