

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

NTUC INCOME INSURANCE CO-OP LTD

1 MARITIME SQUARE

#10-01 HARBOURFONT CENTRE

SINGAPORE 099253

SGP8002A

ESTIMATE

VEHICLE NO SMH3892B
MAKE/MODEL HONDA CIVIC
ACC DATE 11.09.2024

*not allowed
du
meray
17/9/24
3 days d/s @ 1700
the HK 1700*

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 REAR BUMPER <i>DD/pe</i>	683.60	683.60 ✓
2	2 REAR BUMPER PDC SENSOR -RH <i>su</i>	212.60	425.20 X
3	1 REAR BUMPER SIDE COVER -RH <i>groat</i>	68.80	68.80 ✓
4	1 REAR BUMPER DIFUSSER <i>cur</i>	190.30	190.30 ✓
5	1 REAR BUMPER REINFORCEMENT <i>DD/Bent</i>	371.60 <i>199.30</i>	371.60 ✓
6	2 REAR BUMPER SIDE BRACKETS -R/L <i>11</i>	45.50	91.00 X
7	2 REAR BUMPER SIDE RETAINERS -R/L <i>11</i>	51.50	103.00 X
8	1 REAR BOOT LID <i>11</i>	761.20	761.20 X
9	1 REAR END PANEL <i>2</i>	457.20	457.20 X
10	1 REAR TAILLAMP -RH <i>Cne</i>	411.20 <i>340.50</i>	411.20 ✓
			3,563.10
		LESS 20%	712.62
			<u>2,850.48</u>

SPECIAL NETT ITEMS:

1	1 (SET) REAR BUMPER CLIP <i>1er</i>	\$	50.00 <i>30</i>
TOTAL		\$	<u>50.00</u>

LABOUR CHARGES :

1	TO CHECK REAR WIRING	40.00 <i>20</i>
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	<i>11</i> 100.00 X
3	TO TUFF KOTE	<i>11</i> 60.00 X
4	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	800.00 <i>500</i>
5	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	800.00 <i>400</i>
		<u>1,800.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL : **4,700.48**

*P-1482.5
208
1186
30
920
2136
1708*