

STYTECH AUTO PTE LTD
 2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub Singapore 417921
 Tel :64448125 Fax : 64453310
 GST Reg .No: 201601539K
 Co.Reg: No: 201601539K

*Not Allowed
 as
 means
 16/9/24
 2/5 @ 2000
 3 days
 We hope that's fine*

VEHICLE No: SLS 5735M

1PC	FRONT BUMPER	Turn	\$498.20 ✓
1PC	FRONT BUMPER SIDE RETAINER O/S	One	\$48.50 ✓
1SET	FRONT BUMPER CLIPS	per	\$50.00 ✓
1PC	FRONT FENDER O/S	n	\$691.00 X
1PC	FRONT FENDER INNER SHIELD O/S	Turn	\$182.50 ✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	per	\$50.00 ✓
1PC	HEADLAMP O/S	One	\$1,198.00 ✓
1PC	FRONT SUPPORT PANEL	n	\$675.00 X
			\$3,393.20
		LESS 20%	\$2,714.56

TO CHECK WIRING	\$50.00 ²⁰
TO SPRAY RUST PROOFING	11 \$30.00 X
TO CONDUCT WHEEL ALIGNMENT	11 \$80.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$600.00 ³⁸⁰
TO SPRAY PAINTING	\$800.00 ⁵⁰⁰
TOTAL	\$4,274.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*2027.2
 202
 1671.76
 900
 2571.76
 202
 2017*