

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

VEHICLE REPAIR ESTIMATE

Vehicle Number : SMM3881G

Date : 14.09.2024

Vehicle Model : KIA CERATO K3

Chassis : KNAF3416MK50459
76

Accident Date : 12.09.2024

TP Ins. BUDGET DIRECT

Original Reg Date : 27.06.2019

Hui Rong

ESTIMATE

11	1 pc	TAILAMP	698.50	698.50	+
12	1 pc	TAILAMP PANELS	298.70	298.70	+
13	1 pcs	TAILAMP INNER SEALER	35.00	35.00	+
14	1 pcs	REAR BUMPER		985.90	2 691
15	1 pcs	REAR BUMPER SMART KEY SENSOR		275.30	+
16	1 pcs	REAR LOWER BUMPER		485.80	+
17	2 pcs	REAR BUMPER RETAINERS	158.30	316.60	+
18	1 pcs	REAR BUMPER LOWER COVER	168.20	336.40	+
21	1 pc	REAR BUMPER REINFORCEMENT		627.50	+
22	2 pc	REAR REINFORCEMENT TOP BRACKETS	98.90	197.80	+
23	3 pc	REAR REINFORCEMENT BOTTOM BRACKETS	94.50	283.50	+
24	2 pc	REAR BUMPER SENSORS	285.80	571.60	+
26	1 pc	REAR FENDER		1,425.30	+
26	1 pc	REAR FENDER AIR DUCT RH		185.20	+
27	1 pc	REAR FENDER INNERTRIM	334.60	334.60	+
28	1 pc	REAR FENDER INNERSHIELD	195.80	195.80	+
30	1 pc	END PANEL		495.80	+
31	1 pc	END PANEL TOP GARNISH		214.60	+
32	1 pc	END PANEL SMART KEY ANTENNA(INNER)		266.80	+

subtotal 8,230.70

less 10% 823.07

total 7,407.63

Special Nett

1	1 set	Rear Number Plate with Holder	50.00	+
2	1 set	Tailamps clips	30.00	+
3	1 set	Rear Bumper Diffuser (Speical)	950.00	+
4	1 set	Rear Bumper Side Skirt Lip RH (Speical)	350.00	+
5	1 PC	Rims	950.00	+
6	1 PC	Tyre	280.00	+
7	1 set	Rear fender inner trim clips	30.00	+
8	1 set	Rear fender inner shield clips	30.00	+

9	1 set	Body Panel Joint Sealant <i>HPM</i>	120.00	+
---	-------	-------------------------------------	--------	---

Labour charge

Panel Beating	1,000.00	450
Spray painting	1,000.00	300
Check Wiring on tailamps	120.00	+
Anti rust	180.00	+
4 Wheel Alightment	150.00	+
Remove and install reverse sensor	120.00	50
Remove and install interior upholstery	120.00	+
\$ 12,887.63		

600

Adrian Li
1/5 16/09/24

02 days

total: 122190

4/5: 950

950

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: