

ASS. REC. BY:

REF:

Smo /

CS / sm024090284 / knp3

C

Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

18/12

86096.50

Cash

(Red, \$767.20, 11%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS - St

Fees

Others

TOTAL

Veh No:

SNA 8073R

Yr Regn:

0A 21

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

(A)

Make:

Honda: Avanza

c.c

1598

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

48644

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH2N41ETNU 206 299

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/9/24

D.O.I.

17/9/2024

Survey held at

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 271A

Vehicle Details

Vehicle No.: SNA8073R

Vehicle to be Exported: No

Intended Deregistration Date: 14 Sep 2024

Vehicle Make: HYUNDAI

Vehicle Model: CN7 AVANTE 1.6 DOHC CVT S

Primary Colour: White

Manufacturing Year: 2021

Engine No.: G4FMMU040385

Chassis No.: KMHLN41ETNU206299

Maximum Power Output: 90.2 kW (120 bhp)

Open Market Value: \$18,476.00

Original Registration Date: 15 Jul 2021

First Registration Date: 15 Jul 2021

Transfer Count: 1

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jul 2031

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 14 Jul 2031

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,821.00

COE Rebate Amount: \$32,677.00

Total Rebate Amount: \$36,427.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 14 Sep 2024

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SNA8073R
OD/SOMPO

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

FAX: 62213302

ATTN: Motor Claim Department

Claim No: ES2400775

Estimate No: ES2400775/WS

Date: 16 Sep 2024

Policy No: D23MTPV01014680

Veh Reg No: SNA8073R

Make/Model: HYUNDAI HYUNDAI
CN7 AVANTE 1.6 DOHC
CVT S

WS Ref: OD/SOMPO

Claim Type: Own Damage

Accident Date: 14/09/2024

NOT Notified

Repairing B4paim

EX TBA

6096.50

5days

Chassis No: KMHLN41ETNU206299

Engine No: G4FMMU040385

Reg. Date: 15/07/2021

Estimate Repair Cost to Vehicle No : SNA8073R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT NUMBER PLATE GARNISH 15	28.00	1 PC	CM 28.00	✓
2 FRONT BUMPER	270.00	1 PC	CM 270.00	✓
3 FRONT BUMPER REINFORCEMENT	220.00	1 PC	By 220.00	✓
4 FRONT BUMPER SPONGE	75.00	1 PC	CM 75.00	✓
5 FRONT BUMPER LOWER SKIRT	70.00	1 PC	DIY 70.00	275 ✓
6 FRONT BUMPER LOWER SKIRT NO.1	40.00	1 PC	CM 40.00	85 ✓
7 FRONT BUMPER CLIP	2.00	6 PC	CM 12.00	✓
8 FRONT BUMPER RIVET PIN	2.50	6 PC	CM 15.00	✓
9 FRT BUMPER LOGO	26.00	1 PC	CM 26.00	✓
10 FRONT BUMPER TOW HOOK COVER	14.00	1 PC	DIY 14.00	✓
11 FRONT GRILLE ASSY	165.00	1 PC	CM 165.00	✓
12 AIR-FILTER DUCTING	36.00	1 PC	CM 36.00	✓
13 FRT SUPPORT PANEL	320.00	1 PC	CM 320.00	✓
14 FRONT SUPPORT PANEL TOP COVER	75.00	1 PC	By 75.00	✓
15 BONNET INNER LOCK	65.00	1 PC	DIY 65.00	70 ✓
16 FRONT RADAR SENSOR	750.00	1 PC	DIY 750.00	2 ✓
17 HEADLAMP	CM 700.00	2 PC	1,400.00	✓
18 AIR-CON CONDENSER	380.00	1 PC	By 380.00	7 ✓
19 RADIATOR	350.00	1 PC	SM 350.00	X
20 RADIATOR FAN ASSY	260.00	1 PC	SM 260.00	X
21 RADIATOR SIDE AIR GUARDS	28.00	2 PC	CNA 56.00	48 ✓
			4,627.00	
	Add 10%		462.70	5,089.70
Special Net				
22 FRONT NUMBER PLATE	35.00	1 PC	By 35.00	✓
23 COOLANT	25.00	1 UNIT	CM 25.00	✓
				60.00
Labour				
24 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
25 PANEL BEATING; REMOVE & REFIX THE DAMAGED RENEW PARTS,REPAIR FRT RH FENDER,BONNET,FRT CHASSIS & REALIGN THE SAME	700.00	1 LA	700.00	600 ✓
26 PUTTY & RESPRAY ON BONNET,FRT BUMPER,FRT FENDERS	700.00	1 LA	700.00	660 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 **FAX:** 62213302
ATTN: Motor Claim Department

Claim No: ES2400775
Estimate No: ES2400775/WS
Date: 16 Sep 2024
Policy No: D23MTPV01014680
Veh Reg No: SNA8073R
Make/Model: HYUNDAI HYUNDAI
CN7 AVANTE 1.6 DOHC
CVT S
Chassis No: KMHLN41ETNU206299
Engine No: G4FMMU040385
Reg. Date: 15/07/2021

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 14/09/2024

Estimate Repair Cost to Vehicle No : SNA8073R

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
27 REMOVE & REFIX, RESET & CALIBRATE FRT RADAR SENSOR	150.00	1 LA	150.00	1,650.00

Total	S\$ 6,799.70
Add GST @ 9%	611.97
Total Amount payable	S\$ 7,411.67

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

6863.70

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SNA8073R
Supp 1

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department


Claim No: ES2400775
Estimate No: ES2400775/WS
Date: 23 Sep 2024
Policy No: D23MTPV01014680
Veh Reg No: SNA8073R
Make/Model: HYUNDAI HYUNDAI
CN7 AVANTE 1.6 DOHC
CVT S
Chassis No: KMHLN41ETNU206299
Engine No: G4FMMU040385
Reg. Date: 15/07/2021

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 14/09/2024

Estimate Repair Cost to Vehicle No : SNA8073R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 HEADLAMP SUPPORT	24.00	2 PC	48.00	
2 FRONT GRILLE COVER PLATE	8.00	2 PC	16.00	
			64.00	
	Add 10%		6.40	70.40
			Total	S\$ 70.40
			GST Amount	S\$ 6.34
			Total Amount payable	S\$ 76.74

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE