



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090289/Aqh3m4
75 BRAS BASAH ROAD	Date:	21/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 5632Z	Veh. Inspected	SLV 1136C
Policy No.	-	Coverage	0
Claim No.	MT/1295508-001	Excess	\$0.00
Assign From	SHAFAWATI	Assign Date	17/09/2024

2. Vehicle Details

Make & Model	HONDA STEPWAGON	C.C	1993
Engine No.	LFA2223317	Year of Reg.	26/03/2024
Chassis No.	RP81033312	Colour	BRONZE
Odometer	42219 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	GOODYEAR	6
L/H Front Tyre	205/60R16	GOODYEAR	6
R/H Rear Tyre	205/60R16	GOODYEAR	6
L/H Rear Tyre	205/60R16	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/09/2024	Inspection Date	17/09/2024 (12:07)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days