



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24090291/Dqp3e2 (N)
50 RAFFLES PLACE #03-03			Date:	24/01/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: SHIANG YI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SND 1466X	Veh. Inspected	SJJ 7207D	
Policy No.	D24MTPV01003258	Coverage (\$)	0.00	
Claim No.	CMTD2402808/SYH	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	16/09/2024	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216D ACTIVE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA2B32080V925787	Colour	BLACK	
Odometer	108243 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R18	MICHELIN	6 mm	
L/H Front Tyre	205/50 R18	MICHELIN	6 mm	
R/H Rear Tyre	205/50 R18	MICHELIN	6 mm	
L/H Rear Tyre	205/50 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/08/2024	Inspection Date	19/09/2024	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	