

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: INDIA INSURANCE

DATE: 12.09.2024

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : MOHAMAD PAUZI BIN KASSIM

Model : YAMAHA T150

Reg : FBS8292Y Chassis : MH3UG131000002072 DOAccident : 26.08.2024

THIRD PARTY CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 FRONT FORK (SET)	\$ 669.00	bt 500
2 FRONT FENDER	\$ 170.00	as 120
3 FRONT FENDER INNER SHIELD	\$ 220.00	dis 120
4 FRONT FAIRING	\$ 350.00	dis 250
5 FRONT FAIRING CENTRE	\$ 280.00	dis 180
6 FRONT FAIRING LAMP	\$ 480.00	am 380
7 FRONT FAIRING INNER FAIRING	\$ 380.00	dl 280
8 FRONT HEADLAMP	\$ 470.00	cut 370
9 FRONT HEADLAMP FAIRING	\$ 310.00	cut 210
10 FRONT HEADLAMP LOWER FAIRING	\$ 330.00	mig 230
11 FRONT SIDE MIRROR LH	\$ 85.00	cut
12 FRONT SIDE MIRROR RH	\$ 85.00	bno
13 FRONT HANDLE BAR	\$ 270.00	Xun
14 FRONT HANDLE BAR GRIP RH	\$ 65.00	cut
15 FRONT BRAKE LEVER RH	\$ 45.00	cut
16 FRONT CLUTCH LEVER LH	\$ 45.00	cut
17 FRONTT STEERING CONE	\$ 165.00	bt 120
18 CHASSIS FRAME		REPAIR
19 ENGINE COVER RH	\$ 420.00	am 320
20 FRONT SIDE FAIRING LH	\$ 360.00	dis 260
21 FRONT SIDE FAIRING RH	\$ 360.00	mig 260
22 RADIATOR	\$ 600.00	bt 450
23 CENTRE FAIRING LH	\$ 280.00	dl 180
24 CENTRE FAIRING RH	\$ 280.00	dl 180
25 REAR FAIRING RH	\$ 330.00	cut 230
26 FRONT FOOT BRAKE RH	\$ 220.00	bt 120
27 FRONT FOOT REST RH	\$ 45.00	dl
28 FRONT FOOT REST BRACKET RH	\$ 165.00	bt 110
29 REAR EXHAUST PIPE	\$ 1,180.00	bt 800
30 REAR EXHAUST PIPE OUTER COVER RH	\$ 210.00	cut 110
31 REAR EXHAUST PIPE OUTER TAILCOVER RH	\$ 170.00	cut 90
32 REAR FOOT REST RH	\$ 45.00	bno
33 REAR FOOT REST BRACKET RH	\$ 165.00	XR
Total Parts :	\$ 9,249.00	
Less 10%	\$ 924.90	
	\$ 8,324.10	

6285
565650

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

34	FRONT NUMBER PLATE	nett	\$	35.00	200
35	FRONT WHEEL RIM	nett	\$	250.00	200
36	FRONT TYRE	nett	\$	250.00	200
37	ENGINE COVER GASKET RH	nett	\$	70.00	80%
38	ENGINE OIL	nett	\$	120.00	80
39	REAR NUMBER PLATE	nett	\$	35.00	200
40	ERP UNIT	nett	\$	190.00	200
41	TO ELECTRICAL WIRING SERVICES		\$	40.00	30
42	TO DISMANTLE & REFIT FRONT UNDERCARRIAGE		\$	150.00	120
43	TO COMPUTER WHEEL BALANCING		\$	60.00	30
44	To remove, refix, realign, adjust and replace all damaged parts.		\$	480.00	450
45	TO UNDERCOATING FOR RUST PROTECTION		\$	50.00	100
46	To respray paint of accident section.		\$	350.00	250
Grand Total :				\$ 2,080.00	1675
				\$ 10,404.10	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Shaun : 97432262

Tanjiu 97445749 / 62563561
'wp' 18/9/24 @ 330pm
* To check repair limit
L/S Resumy after repair
Tanjiu e/khant-u
5 days

5656.50
1675
7331.50
415\$5850
5 days
#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____