

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/24090316/UVH3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLE 297R/

at Workshop m/s

Car Smith

of

Insured:

SNJ9307M

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

826k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3 517A

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 13458

Veh No:

SLE 297R/

Yr Regn:

15/07/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Honda Shuttle

c.c

1496

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

335883

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

6K81003923

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

At order

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

0

mm

L/Bal.

6

mm

D.O.A.

13/09/24

D.O.I.

18/09/24

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/9/24 2/5 @ 5100 22713 17h. in hand Alex

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	517A
Vehicle Details	
Vehicle No.:	SLE2978Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B3534657
Chassis No.:	GK81003923
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,130.00
Original Registration Date:	15 Jul 2016
First Registration Date:	15 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$7,130.00 3865
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2026
PARF Rebate Amount:	\$3,921.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$9,538.00
Total Rebate Amount:	\$13,459.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 17 Sep 2024

OK



PREMIUM AD

Honda Shuttle
Hybrid 1.5A

\$36,888

Instl. \$1,129

/mth

\$16,390 /yr

3 Owners

24-Oct-2016

(2yrs 1mth COE left)

N.Air 1,496 cc

Petrol-Electric

Reliable and well maintained by previous owner, spacious, full loan available, high trade in. Warranty provided! Call to arrange for a viewing and test drive now!


SH Vehicle Traders Pte Ltd|Posted 14-Sep-2024

☐ Compare

★ StarAd View All

cheapest mini cooper in the market. Dont miss!

low mileage. Fully agent maintained. cheapest in the market. dont miss ... Car Empire



Honda Shuttle
1.5A G

\$25,900

Instl. \$1,045

/mth

\$13,850 /yr

1 Owner

25-Apr-2016

(1yr 7mths COE left)

83,900 km 1,496 cc

1 Owner Unit. Well Maintained Interior With Original Paintwork And No Repair Required. Non Private Hire/Leasing Car. Bank/In House Full Loan Financing Available And We Accept Cash Deal For Immediate Transfer Of Ownership. Brand New Paintwork And Servicing Package Will Be Provided. Contact Us To View This Unit Now!

Posted 13-Sep-2024

☐ Compare

PREMIUM AD

Honda Shuttle
1.5A G

\$23,800

Instl. \$1,076

/mth

\$14,280 /yr

1 Owner

02-Mar-2016

(1yr 5mths COE left)

127,000 km 1,496 cc

Non-PHV vehicle! Well maintained by previous 1 owner with serviced record history! Very good condition! 100% accident free! Very low mileage done, guarantee best condition in the market. High loan available and trade in are welcomed. Call to make appointment!

Posted 13-Sep-2024

☐ Compare[Compare](#)

CARSMITH PRIVATE LIMITED

PREMIER@8 KAKI BUKIT AVE 4 #04-35 Singapore 415875

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: SLE2978Y

MAKE & MODEL: HONDA SHUTTLE

DOA: 13.09.2024

CLAIM TYPE: TP CLAIM

Not Authorized
for
claims
18/9/24
d/s \$5100/
6 days.
Telephone Attorney

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE 1193	1	\$ 1,864.00	DD Bent ✓
TAILGATE INNER TRIM BOARD	1	\$ 390.00	11 X
TAILGATE WEATHERSTRIP	1	\$ 197.00	11 X
TAILGATE INNER LOCK	1	\$ 286.00	11 X
TAILGATE DAMPER LH	1	\$ 231.00	11 X
TAILGATE DAMPER RH	1	\$ 231.00	11 X
TAILGATE LOGO	1	\$ 98.00	11 X
TAILGATE EMBLEM 'SHUTTLE' 80	1	\$ 95.00	11 X ✓
TAILGATE OUTER GARNISH	1	\$ 393.10	11 X
TAILGATE INNER HANDLE GARNISH	1	\$ 78.00	11 X
TAILGATE CHROME MOULDING GARNISH	1	\$ 268.00	Sub ✓
TAILGATE WIPER MOTOR	1	\$ 485.00	11 X
TAILGATE LAMP LH	1	\$ 358.00	11 X
TAILGATE LAMP RH	1	\$ 358.00	Bnd ✓
TAILLAMP RH 520.00	1	\$ 690.60	3nd ✓
TAILLAMP PANEL RH	1	\$ 204.60	DD ✓
REAR QUARTER GLASS RH	1	\$ 576.30	11 X
REAR QUARTER GLASS WEATHERSTRIP RH	1	\$ 165.80	11 X
WINDSCREEN	1	\$ 1,230.00	11 X
WINDSCREEN MOULDING 110.20	1	\$ 256.00	11 X ✓
REAR END PANEL	1	\$ 910.00	12 X
REAR END PANEL TOP GARNISH	1	\$ 187.00	11 X
REAR BUMPER 936.00	1	\$ 1,530.00	Torn ✓
REAR BUMPER LOWER GARNISH	1	\$ 526.00	NF X
REAR BUMPER SIDE RETAINER LH	1	\$ 120.20	11 X
REAR BUMPER SIDE RETAINER RH 68.50	1	\$ 120.20	Grd ✓
REAR BUMPER BRACKET LH	1	\$ 98.00	NS X
REAR BUMPER BRACKET RH	1	\$ 98.00	NS X
REAR BUMPER SPONGE @ SGD 98	2	\$ 196.00	N/S on 2/5 Torn pc
REAR BUMPER TOW COVER	1	\$ 48.00	7m ✓
REAR BUMPER REFLECTOR GARNISH RH 118.00	1	\$ 169.00	7m ✓
REAR BUMPER REFLECTOR RH 66.00	1	\$ 145.00	one ✓
REAR FENDER RH 1021.20	1	\$ 1,451.00	72/3m ✓
REAR FENDER INNER SHIELD RH	1	\$ 325.00	11 X
REAR FENDER INNER PANEL RH	1	\$ 2,234.00	12 X

\$ 16,612.80

LESS 20% \$ 3,322.56

SUB TOTAL \$ 13,290.24

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	11 40 S/N

TAILGATE INNER SEAL	1	\$	50.00	11 X
TAILGATE SEALANT	1	\$	100.00	11 X
TAILGATE TRIMBOARD CLIPS	1 SET	\$	50.00	11 X
COATING	1	\$	600.00	11 X
REAR NUMBER PLATE	1	\$	80.00	11 X
REAR BUMPER CLIPS	1 SET	\$	50.00	11 405/n
REAR END PANEL SEALANT	1	\$	80.00	11 X
REAR END PANEL TOP GARNISH CLIPS	1 SET	\$	50.00	11 X
REVERSE SENSOR	1 SET	\$	480.00	11 X
REAR REVESE CAMERA	1	\$	450.00	11 X
SUB TOTAL			\$ 2,090.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	20
TO REMOVE AND REFIT REAR TAILGATE GLASS TO FACILITATE THE REPAIR	1	\$ 200.00	120
TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	1	\$ 100.00	50
TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.	1	\$ 200.00	60
TO MEASURE, DRILLS HOLES ON ^{refit} REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	1	\$ 80.00	30
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	900
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,600.00	1000
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	50

SUB TOTAL \$ 3,980.00

GRAND TOTAL \$ 19,360.24

LKK Auto Consultants hereby notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts for the customer
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5089.50
202
4071.60
80
2230
6381.6
202
5105