

SPEEDWERKZ PRIVATE LIMITED
 1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883
 Tel: 96195936 / info@speedwerkz.biz

not Authorized
 den
 mora-s
 19/9/24
 d/s 6000/
 S-dm r.
 telephone. At. my

VEHICLE NUMBER: SMH5288H
 MAKE & MODEL: HONDA SHUTTLE

TAILGATE	Body ID	1193	\$1,522.50	/
TAILGATE H LOGO	rel		\$52.10	/
TAILGATE "SHUTTLE" EMBLEM	rel		\$68.30	/
TAILGATE HINGES L/R X2	11		\$188.80	x
TAILGATE NUMBER PLATE LAMP L/R X2	11		\$146.60	x
TAILGATE OUTER GARNISH	cut/cue		\$342.80	/
TAILGATE OUTER GARNISH CHROME	cut		\$143.70	/
TAILGATE SHOCK ABSORBER L/R X2	11		\$416.20	x
TAILGATE LAMP L/R X2	cue	385x2=770	\$996.60	/
TAILGATE OUTER HANDLE	11		\$241.30	x
TAILGATE INNER HANDLE POCKET	11		\$79.60	x
TAILGATE INNER LOCK	cut		\$218.20	/
TAILGATE STRIKER	11		\$56.00	x
TAILGATE WEATHERSTRIP	11		\$198.70	/
TAILGATE WINDSCREEN MOULDING	rel		\$86.30	/
TAILGATE INNER TRIMBOARD	de/torn		\$379.30	/
TAILGATE INNER PULL POCKET	11		\$78.90	x
TAILGATE WIPER MOTOR	11		\$528.00	x
TAIL LAMP L/R X2	cue	480x2=960	\$1,256.80	/
REAR BUMPER	11	936	\$1,268.10	/
REAR BUMPER TOW COVER	11		\$86.30	x
REAR BUMPER SIDE RETAINER L/R X2	11		\$86.00	x
REAR BUMPER SIDE BRACKET L/R X2	11		\$79.60	x
REAR BUMPER TOP CHROME	NZ		\$186.90	x
REAR BUMPER SPONGE	11		\$128.10	x
REAR BUMPER REFLECTORS L/R X2	11		\$196.80	x
REAR BUMPER REFLECTOR GARNISH L/R X2	11		\$246.40	x
REAR BUMPER BUZZER	11		\$96.40	x
REAR BUMPER ANTENNA	11		\$162.70	x
END PANEL	DD/3ent	517.00	\$682.70	/
END PANEL GARNISH	11		\$202.10	/
REAR FENDER INNER TRIMBOARD L/R X2	N/1800 04 Torm 425.80		\$986.20	17 C
FLOOR PANEL	11		\$1,352.30	x
FLOOR PANEL COMPARTMENT TOP COVER	11		\$586.90	x
FLOOR PANEL COMPARTMENT TRAY	cue		\$305.60	/
REAR EXHAUST HEAT SHIELD	11		\$89.00	x
			\$13,742.80	
			Less 20%	
			\$2,748.56	
			\$10,994.24	

1 set	REAR REVERSE sensor	malfunction	\$300.00	200	S/W
1 set	REAR BUMPER CLIPS	new	\$60.00	30	S/W
	REAR BUMPER STICKER	new (1214)	\$180.00	X	
1 set	TAILGATE TRIMBOARD CLIPS	new	\$50.00	30	S/W
	TAILGATE OUTER GARNISH CLIPS	new	\$30.00	X	
	TAILGATE STICKER	new (1214)	\$200.00	X	
	TAILGATE WINDSCREEN SEALANT	new	\$100.00	40	S/W
	TAILGATE WINDSCREEN SPONGE	new	\$60.00	20	S/W
	END PANEL GARNISH CLIPS	new	\$60.00	X	
	END PANEL SEALANT	new	\$100.00	X	
	REAR NUMBER PLATE WITH GARNISH	Daye	\$70.00	35	S/W
			\$1,490.00		

TO CHECK REAR WIRING	\$50.00	20
TO REPLACE REAR REVERSE SENSOR	\$80.00	30
TO REMOVE AND REFIT REAR REVERSE CAMERA	\$100.00	X
TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW	\$100.00	50
TO REMOVE AND REFIT REAR WINDSCREEN	\$180.00	120
TO REMOVE AND REPLACE REAR INTERIOR TRIMS AND GARNISH	\$120.00	60
TO PROVIDE LABOUR, WORKMANSHIP	\$1,600.00	600
TO SPRAY PAINT ON AFFECTED PANELS	\$1,600.00	800
RUST PROOFING	\$150.00	50
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	\$150.00	X
		\$4,130.00

Total

\$16,614.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-67989
 202
 5439.12
 355
 1730
 7524.12
 202
 6019