(08/11/13) wef REF: CS/SMR 240°	30327/Rgp3 Tqp3 307R
A STATE OF THE STA	NMENT
Estimated Cost: OD TP WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: SMD 8456 C	Veh No: SMD 8456R Yr Regn: 2016 July Type: M.Ca) / M.Cycle / Bus / Van / Lorry / Tact / Prime Mover / Truck / Trailer or Make: Hunda VEZUL (-5X CVT c.c. 1496 Colour BLUG AC: Insured / Std / NI / NA
at Workshop m/s CYULE & CARLINGS of 90% famous and	Sp.Reading = 195593 T/Radio: Insured J Std / N1 / NA Eng/No: C/No: RUI 111 6042
Claims No. Sum Insured: Excess: (Client's Record)	Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: norder / Jammed / Leaked / Burnt or Modi: Nil / S/Rish / STD A/Rim or
Make of Veh: (Policy Condition) Remore: The set had commenced its N/S O/S	Tyre Size: F: 2/5/66/6 R: 7 BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
repair at the time of inspection.	TOYO PIONE OF
Bal or Market Value: 32 Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No	Front R/Bal. mm R/Bal. mm L/Bal. mm
Est Repairs: 7 days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	Survey held at PANDAN G
CA / REV REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roomop or CEALO S The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted:	THE UIC I CHESS HARRE I DOUT GRANDER WITH THE
Date / Time Action / Instruction REPAIL LIMIT (GK Taufikh finalised \$4573.40, 7 days (Red \$5088.90, 53%)
	Days Of Repair: 7 Resurvey No. of Trip: 1 Survey Fee: Transportation: Site Insp (\$) S+RS_S
Report Format: TP Lump Sum / I.B.I: (\$)	: Interview (\$) Photos : Tech. Invs (\$) Others : Weekend (\$)



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H GST Reg No. MR-8500111-X

Owner Name & Vehicle Info

STIMATE

Cycle & Carriage Leasing Pte. Ltd.

Reg No/Reg Date SMD8456R

Invoice Name & Address

| Reg No/Reg Date | SMD8456R | / 01/07/2016 | 239 Alexandra Road | Date In/Mileage | / 0 | Singapore 159930 |

Chassis No RU11116042
Engine No L15B4036046

Contact No Make/Model VEZEL 1.5X CVT

Ac	count No	Terms	Date/Time Printed	CSE	Operator		WIP No		
RC	000162		17/09/2024/ 15:52		1210/ Lim Teng Keat		33594		
5%			Description of Goo	ds / Services		Qty	Unit Price	Disc%	Amount
Z	TEXT TP CLAIM DOA 12/09 SUR	9/2024				į			
E		E BOOT L	ID, REAR BUMPER AND F FFECTED AREA	REAR END PANEL					625 2250.00
£	PNT98000		UMPER, TAIL GATE, REA	AR FND PANEL					300 1600.00
M	CHAIR DV					1			50 180.00
M	SUNDRY	PODV SEA	ANT ON AFFECTED APE	SI	ma				50 186.00
E	PNIOOUUU								160 280.00
	PNT88000		INDSCREEN						50 100.00
	SUNDRY		LEAK AFTER WINDSCREEN	N REPLACEMENT					160 350.00
Α	TO SUPPLY 54900099		CHASSIS ELECTRICAL S	SYSTEM					50 100.00
A	10028901		NOSTIC CHECK ON ELECT		SYSTEM				160 280.00
M	SUNDRY SUNDRIES	OUT DIAG	NOSTIC CHECK ON LELCT	KONTO CONTROL	3131211				20 88.00
M	SUNDRY TAIL GATE	U _							1093.40
M	SUNDKY	_							115.10
M	TAIL GATE SUNDRY		<u> </u>						40.00
M	TAIL GATE SUNDRY	STRIKER	Xnn						107.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H GST Reg No. MR-8500111-X

TIMATE

Invoice Name & Address

Owner Name & Vehicle Info

Cycle & Carriage Leasing Pte. Ltd.

Reg No/Reg Date

SMD8456R

/ 01/07/2016 0

239 Alexandra Road Singapore 159930

Contact No

Date In/Mileage

RU11116042

Chassis No **Engine No**

L15B4036046

Make/Model

VEZEL 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
RC000162		17/09/2024/ 15:52		1210/ Lim Teng Keat		33594		
		Description of Good	ls / Services	¥	Qty	Unit Price	Disc%	Amount
M SUNDRY TAIL GATE M SUNDRY TAIL GATE M SUNDRY REAR WIND M SUNDRY REAR WIND: M SUNDRY REAR BUMPE M SUNDRY	E HONDA LO E VEZEL EN OSCREEN SI OSCREEN SI OSCREEN SE SCREEN SE SCREEN SE SCREEN FA ER AL ER RHS CO ER RHS RE	STRIP X Xnn OGO X X nn MBLEM A X X nn EAL TOP M X EAL HS A X EAL BOTTOM M ASTERNER M OVER CAT	LK the • To • To • Po • Ti • No • So • So	EYOR NAME : FORME	irvey i judice" basis eyed <u>and</u>			32.30 31.10 879.00 45.0 45.0 45.0 46.0 401. 121.

Confirm & accepted by

the removal of the windscreen.

Nett

8,587.30

Total Payable

8,587.30

Authorized signatory and company stamp

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after many head of the require required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to a cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


/ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	307R
Vehicle Details	
/ehicle No.:	SMD8456R
/ehicle to be Exported:	No
ntended Deregistration Date:	26 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4036046
Chassis No.:	RU11116042
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,067.00
Original Registration Date:	01 Jul 2016
First Registration Date:	01 Jul 2016
Fransfer Count:	1
Actual ARF Paid:	\$10,094.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2026
PARF Rebate Amount:	\$5,551.00
ntended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$9,721.00
Total Rebate Amount:	\$15,272.00
Message	

The information contained herein is correct as at 26 Sep 2024

m.sgcarmart.com














Honda Vezel 1.5A X

\$34,800 Instalment \$1,210/mth

(\$) Apply for 2.48% loan









Overview Financial Photo Research

Depreciation

(i) \$15,530 / year

Reg. Date

15-Aug-2016 (1yr 10mths 19days COE left)

Manufactured

(i) 2016

Mileage

Auto

Transmission

1,496 cc

Engine Cap

(i) \$682 / year

Road Tax

Power

96.0 kW (128 bhp)

Curb Weight

(i) 1,190 kg

COE

OMV

\$52,503

\$20,805

ARF

\$11,127

Dereg Value

(i) \$16,002 as of today

No. of Owners

(i) 2