

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GABRIEL WEE

Date: 03/10/2024

PRELIMINARY ADVICE

Vehicle No	SMZ 8845K	Accident Date	03/09/2024
Make	HYUNDAI IONIQ EV (A)	Policy No.	D19MFL0000111_05
Assignment Date	18/09/2024	Excess	-
Inspection Date	23/9/2024	Est. Duration of Repair	4 days

Inspected At: Komoco Motors Pte Ltd

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$12,601.20
Revised Estimate Amount:	\$5,160.40
"Check" Items Amount	\$3,503.60
Total	\$8,664.00

Total Loss Consideration

Book Value	\$0.00
Market Value	\$0.00
COE / PARF Rebate	
Salvage Value	\$0.00
Margin for Repair	

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.