



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLA6670D
Chassis No : JHMGR3830MS228759
Model : JAZZ H-LUXE E-CVT 21YM
Owner's Name : LAI CHEE LEONG
Ins Policy No. :
Date of Accident : 14/9/2024

Document No. : SQT24002532
Date : 17. Sep 2024
Customer No. : WZF002
Svc Advisor :
Engine No : LEB81040704
Date | Time : 17. Sep 2024 7:10:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
71501-TZA-000ZD	FACE,RR.BUMPER NH902P Xnn	1	638.20	25	478.65	43.08	521.73
71630-TZA-003	SPACER,R.RR.BUMPER SIDE Xnn	1	19.10	25	14.32	1.29	15.61
71680-TZA-003	SPACER,L.RR.BUMPER SIDE Xnn	1	19.10	25	14.32	1.29	15.61
91505-TM8-003	CLIP,BUMPER Xnn	2	2.30	25	3.45	0.31	3.76
04636-TZA-300ZZ	PANEL SET,R.RR.OUTSIDE bt ✓	1	744.50	25	558.37 ✓	50.25	608.62
73500-TZB-G01	GLASS ASSY,R.QUARTER WINDSHIELD m ✓	1	276.50	25	207.37 ✓	18.66	226.03
BO-WS-SEALANT	WINDSCREEN SEALANT (N) m ✓	1	60.00		60.00 ✓	5.40	65.40
42700-TZA-J71	DISK,ALUMINIUM WHEEL 16X6J sur ✓	1	939.50	25	704.62 ✓	63.42	768.04
67510-TZA-J20ZZ	PANEL COMP,R.RR.DOOR bt ✓	1	738.20	25	553.65 ✓	49.83	603.48
75313-TZA-J21	MOLDING ASSY,R.RR.DOOR LOWERN ✓	1	91.50	25	68.62 ✓	6.18	74.80
Sum Item					<u>2663.37</u>	<u>239.71</u>	<u>2,903.08</u>
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS. 1 ✓	1	250.00 ✓		250.00	22.50	272.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4 1 ✓	1	220.00 ✓		220.00	19.80	239.80
Sum Ext. Service					<u>470.00</u>	<u>42.30</u>	<u>512.30</u>
BOSUN	SUNDRIES 1	1	110.00 30 ✓		110.00	9.90	119.90
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N) 1	1	250.00 180 ✓		250.00	22.50	272.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER 1	1	250.00 180 ✓		250.00	22.50	272.50

Printed on 17/9/2024 7:20:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SLA6670D
Chassis No : JHMGR3830MS228759
Model : JAZZ H-LUXE E-CVT 21YM
Owner's Name : LAI CHEE LEONG
Ins Policy No. :
Date of Accident : 14/9/2024

Document No. : SQT24002532
Date : 17. Sep 2024
Customer No. : WZF002
Svc Advisor :
Engine No : LEB81040704
Date | Time : 17. Sep 2024 7:10:02 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	650.00		650.00	58.50	708.50
BG52R	REPLACE RR. R QTR GLASS.(N)	1	480.00		480.00	43.20	523.20
BOBC	BODY UNDERSIDE COATING (N)	1	520.00		520.00	46.80	566.80
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00		650.00	58.50	708.50
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	4000.00	2600	4000.00	360.00	4360.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3200.00	1560	3200.00	288.00	3488.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	58.50	708.50
BMU02R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)	1	1500.00	X 11	1500.00	135.00	1635.00
BOSUN	REMOVE AND REPLACE RHR WHEEL/RIM/TYRE	1	60.00		60.00	5.40	65.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	580	650.00	58.50	708.50
Sum Labor					12970.00	1,167.30	14,137.30

Survey By

Date & Time

Excess

Status

Signature

Rasul - Hp 9001668

16/10/24

7 days

for Reg 54 print

Total Amount 16,103.37 1,449.31 17,552.68

Total (Inclusive of GST) 17,552.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/9/2024 7:20:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0136921 / LAI CHEE LEONG
Chassis No: JHMGR3830MS228759
License No: SLA6670D
Mileage: 31327
Engine No: LEB81040704

Document No: SVO24038825
Printed By: SHNG
Order Date: 16. October 2024
Order Time: 1:52:06 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	9% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
67825-TZA-J01	TAPE,R.RR.DOOR SASH ROOF	1	21.30	25	15.97	1.44	17.41
72910-TZA-J01	MOLDING ASSY,R.RR.DOOR	1	44.70	25	33.52	3.02	36.54
	SUM PARTS:				49.49	4.46	53.95
	TOTAL SGD				49.49	4.46	53.95

Total Payable (SGD) 53.95

GST Amount is calculated from individual line(s)