

STYTECH AUTO PTE LTD

2 Kaki Bukit Ave 2 #01-03

Kaki Bukit Autohub Singapore 417921

Tel : 64448125 Fax : 64453310

GST Reg .No: 201601539K

Co.Reg: No: 201601539K

Not Authorized
merant
20/9/24
4 days. 2/5 \$3800
Edupho After repair

VEHICLE No: PC 3806S

LIST ITEM

1PC	FRONT BUMPER
1PC	FRONT BUMPER SIDE HOLDER N/S
1SET	FRONT BUMPER CLIPS
1PC	FRONT FOG LAMP COVER N/S
1PC	HEADLAMP LED N/S
1PC	FRONT CORNER PANEL N/S
1PC	FRONT DOOR N/S
1PC	FRONT STEP PANEL GARNISH N/S
1PC	FRONT STEP PANEL N/S
1PC	FRONT VIDEO CAM ASSY N/S

Torn	\$788.20 ✓
Scr	\$217.70 X
Scr	\$45.00 ✓
Scr	\$96.90 ✓
Cre	\$3,668.20 ✓
DD/3ent	\$455.20 ✓
R	\$1,866.20 X
Cur	\$283.20 ✓
R	\$350.50 X
Scr	\$900.00 X

\$8,671.10

LESS 25% \$6,503.33

TO CHECK WIRING
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO SPRAY PAINTING

\$50.00 20

\$120.00 30

\$800.00 350

\$1,000.00 350

TOTAL \$8,473.33

QV Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts for resurvey
• All prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2- 5336.7
252
4002.53
750
4752.53
202
3602.