

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	16:59
ACCIDENT DATE	13-Sep-24
BUS CAPTAIN NAME	PANG MAN LIN
THIRD PARTY CLAIM AGAINST	SMRT

BUS REGISTRATION NUMBER	SBS3372H
BUS TYPE (SD/DD)	DD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	CCTV BUZZER AND BRACKET	1	\$ 836.00
		9% GST	\$ 75.24
		PARTS TOTAL COST	\$ 911.24

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- DISMANTLE AND REPLACE ITEM NO : 1	\$ 650.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- OSR DOME	\$ 650.00
SPRAY PAINTING :- OSR DOME	\$ 640.00
SPRAY PAINTING \$640 PER PANEL	9% GST \$ 174.60
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST \$ 2,114.60

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	13/Sep/2024
	DATE & TIME SURVEY	
	DATE OUT	
BUS TYPE (SD / DD)	DD	TOTAL NUMBER OF DAYS 5
LOSS OF USE COST		\$2,000.00

SUMMARY	
SECTION NO.	COST
1	\$ 911.24
2	\$ 2,114.60
3	\$ 2,000.00
TOTAL	\$ 5,025.84