

ESTIMATE

17/9/2024

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Vehicle No: SNE6444X
Vehicle Model: KIA NIRO
Est No: CBMQ24090165
Claims ref:
Accident Date: 13/09/24
In Charge: HENRY
Remarks:

Automotive Pte Ltd
Main Office:
Main Building
No. 22, Jalan Klang
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5551
www.mova.com.sg
Workshop Dept:
Block 10/06,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198804033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	REAR BUMPER <i>cm</i>	1	PC \$ 621.80	\$ 621.80
2	REAR BUMPER RETAINER RH <i>Xan</i>	1	PC \$ 64.40	\$ 64.40
3	REAR BUMPER RETAINER LH <i>Xan</i>	1	PC \$ 64.40	\$ 64.40
4	REAR BUMPER REINFORCEMENT <i>?cm</i>	1	PC \$ 805.40	\$ 805.40 <i>288</i>
5	REAR BUMPER TOW CAP <i>Xan</i>	1	PC \$ 80.50	\$ 80.50
6	REAR BUMPER LOWER DIFFUSER <i>scu</i>	1	PC \$ 248.50	\$ 248.50
7	REAR BUMPER SIDE GARNISH LH <i>Xan</i>	1	PC \$ 195.50	\$ 195.50
8	REAR BUMPER REFLECTOR LH <i>Xan</i>	1	PC \$ 322.60	\$ 322.60
9	END PANEL <i>?xscu</i>	1	PC \$ 525.20	\$ 525.20
10	END PANEL UPPER GARNISH <i>Xan</i>	1	PC \$ 195.50	\$ 195.50
11	TAILGATE LOCK <i>Xan</i>	1	PC \$ 310.50	\$ 310.50
12	BOOT RUBBER <i>Xan</i>	1	PC \$ 148.40	\$ 148.40
13	REAR REVERSE SENSOR <i>Xan</i>	1	SET \$ 280.00	\$ 280.00

LIST TOTAL S\$

10% DISCOUNT S\$

1158.30

10%

1042.47

\$ 3,862.70

\$ (386.27)

\$ 3,476.43

SPECIAL NET ITEMS:

1	REAR NUMBER PLATE & FRAME <i>Xan</i>	1	PC \$ 45.00	\$ 45.00
---	--------------------------------------	---	-------------	----------

SPECIAL NET TOTAL S\$

\$ 45.00

LABOUR CHARGE:

1	BODY REPAIR, PANEL BEAT & STRAIGHTEN . RE-ALIGN ACCIDENT AREAS	\$ 600.00 <i>300</i>
2	SPRAY PAINT - REAR BUMPER, TAILGATE & END PANEL	<i>560</i> \$ 600.00 <i>200</i>
3	REMOVE & REFIT REVERSE SENSOR - HARNESS & COMPONENTS	\$ 150.00 <i>60</i>
4	ALIGN TAIL LAMP , REVERSE SENSOR HARNESS & CHECK WIRING	\$ 100.00 <i>XM</i>

* This is a computer generated letter and does not need a signature.

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Vehicle No: SNE6444X
Vehicle Model: KIA NIRO
Est No: CBMQ24090165
Claims ref:
Accident Date: 13/09/24
In Charge: HENRY
Remarks:

WORKSHOP: DUBAI
Workshop: Dubai
Tel: (05) 6212 8882
Fax: (05) 6212 8882
Email: info@lkkauto.com
GST Reg: 142-0000004-2

No	Description	Qty	U. Price	Amounts S\$
5	RUST PROOFING <i>XAN</i>			\$ 100.00
TOTAL LABOUR COST S\$				\$ 1,550.00

AMOUNT S\$ \$ 5,071.43
GST @ 9% \$ 456.43
AMOUNT DUE S\$ \$ 5,527.86

Customer's Signature

Spunk
MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
1042.47 - P Hy 90010068
560.00 - L
341.00 - Supp. P 3 days
1943.47 - T P/P

30/09/24

Rey 54 paint

email: rasul@lkkauto.com

* This is a computer generated letter and does not need a signature.

SUPPLEMENTARY LIST FORM

SURVEYOR / INSURER

VEHICLE NUMBER

VEHICLE MODEL

DATE _____

. Rasul @ LKPK

SNE 6444 X

: KHA NIRO

: 20/11/2024

[illegible]

Henry
ESTIMATOR

Rasul
SURVEYOR

Rep
Lump