



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24090344/Anp3e2(N)
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	13/03/2025
HEMMANT ROAD SINGAPORE 438675			
ATTN: LAI PENG CHONG		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 225R	Veh. Inspected	SNA 1792U
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/048 (LK)	Excess (\$)	0.00
Assign From	LAI PENG CHONG	Assign Date	18/09/2024
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHLN41ETNU184795	Colour	GREY
Odometer	145839 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	KAPSEN	6 mm
L/H Front Tyre	215/45 R17	KAPSEN	6 mm
R/H Rear Tyre	215/45 R17	KAPSEN	6 mm
L/H Rear Tyre	215/45 R17	KAPSEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/09/2024	Inspection Date	25/09/2024
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #01-15 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	