

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : **Mohammad Imran Bin Kassim (89255438)**

Accident Date : **10-Sep-24**

Vehicle No : **SMM6440 (DOR: 180324)**

Vehicle Moc **Yamaha 135LC (F1)**

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
2	Front fork tube assy <i>n x</i>	\$ 640.00 X
1	Fork under bracket <i>n x</i>	\$ 225.00 X
1	Front sport rim <i>2 x</i>	\$ 760.00 X
1	Front rim shaft <i>n x</i>	\$ 125.00 X
1	Front rim bearing <i>n x</i>	\$ 90.00 X
1	Front brake disc <i>n x</i>	\$ 235.00 X
1	Headlamp assy <i>one</i>	\$ 680.00 ✓
1	Headlamp cover <i>one</i>	\$ 140.00 ✓
1	Handle bar <i>set</i>	\$ 145 280.00 ✓
1	Handle bar end <i>1/5 (u)</i>	\$ 40 115.00 ✓
1	Hand grip (1 set) <i>5 u x</i>	\$ 95.00 X
1	Pilot light <i>one</i>	\$ 350 485.00 ✓
2	Side mirrors <i>one</i>	\$ 140.00 ✓
1	Front cover - matt <i>one</i>	\$ 160.00 ✓
1	Front side cover (matt) <i>one</i>	\$ 160.00 ✓
1	Fairing assy (1 set) <i>one</i>	\$ 580 750.00 ✓
1	Basket <i>one</i>	\$ 60 125.00 ✓
1	Front footrest bracket <i>set</i>	\$ 110 180.00 ✓
2	Front footrest rubbers <i>70/11/100</i>	\$ 60 90.00 ✓
1	Side stand <i>n x</i>	\$ 135.00 X
1	Rear footrests <i>one</i>	\$ 60 105.00 ✓
1	Rear footrest brackets <i>n x</i>	\$ 185.00 X
1	Gear pedal <i>one</i>	\$ 80 125.00 ✓
		\$ 6,025.00
	Less 10%	\$ 602.50
		\$ 5,422.50

Special Net Items

1	Number plate (1 set) <i>5 u x</i>	\$ 38.00 X
2	Fork oils <i>n x</i>	\$ 30.00 X
2	Fork oil seals <i>n x</i>	\$ 56.00 X
1	Steering cone (1 set) <i>n x</i>	\$ 90.00 X
1	Rear box <i>one</i>	\$ 580.00 400

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : **Mohammad Imran Bin Kassim (89255438)**

Accident Date : **10-Sep-24**

Vehicle No : **SMM6440 (DOR: 180324)**

Vehicle Model : **Yamaha 135LC (F1)**

Estimated Repair Costs

1	Rear box bracket	Λ Λ X	\$	180.00
			\$	974.00


S/No. Labour

1	To provide towing service (LOD)	refer 202 X	\$	-
2	To check wiring and reset headlamp focusing		\$	11 80.00 X
3	To provide labour		\$	460.00 300
4	To repair body frame		\$	11 480.00 X
			\$	1,020.00

Grand Total

\$ 7,416.50

Singapore Dollars: Seven Thousand Four Hundred Sixteen and Cents: Fifty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2765
102
248850
400
300