

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Ong Ga Hwa (91263247)

Accident Date : 01-Sep-23

Vehicle No : JTL5352 (DOR: 11062019)

Vehicle Model : Yamaha YZF-R25

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Fork tube assy - L/H <i>SLC</i>	\$ 980.00 <i>X</i>
1	Fork tube assy - R/H <i>Dange / MD</i>	\$ <i>800</i> 980.00 <i>✓</i>
1	Fork under bracket <i>TW1</i>	\$ <i>325</i> 480.00 <i>✓</i>
1	Front rim <i>11 X</i>	\$ 385.00 <i>X</i>
1	Front rim shaft <i>11 X</i>	\$ 120.00 <i>X</i>
1	Front rim bearing <i>11 X</i>	\$ 90.00 <i>X</i>
1	Headlamp assy <i>CNE</i>	\$ <i>600</i> 980.00 <i>✓</i>
1	Headlamp cover <i>CUT</i>	\$ <i>145</i> 180.00 <i>✓</i>
1	Lampstay <i>Best</i>	\$ <i>200</i> 380.00 <i>✓</i>
1	Front top inner cover <i>CUT</i>	\$ 110.00 <i>✓</i>
1	Front side inner cover - matt <i>CNE</i>	\$ 165.00 <i>✓</i>
1	Handle-bar - L/R/H <i>Best</i>	\$ <i>280</i> 400.00 <i>✓</i>
1	Hand grip <i>TO.1</i>	\$ 88.00 <i>✓</i>
1	Handle bar end <i>MS X</i>	\$ 110.00 <i>X</i>
2	Mirror - L/R/H <i>CUT</i>	\$ <i>190</i> 360.00 <i>✓</i>
1	Front signal (1 set) <i>CNE</i>	\$ <i>100</i> 150.00 <i>✓</i>
1	Gear pedal <i>CUT</i>	\$ <i>115</i> 165.00 <i>✓</i>
1	Brake pedal <i>2 X</i>	\$ 180.00 <i>X</i>
1	Front footrest (1 set) <i>CUT</i>	\$ <i>160</i> 230.00 <i>✓</i>
1	Front footrest bracket <i>CUT</i>	\$ <i>190</i> 380.00 <i>✓</i>
1	Rear footrest (1 set) <i>CUT</i>	\$ <i>100</i> 200.00 <i>✓</i>
1	Rear footrest bracket - L/H <i>CUT</i>	\$ <i>190</i> 250.00 <i>✓</i>
1	Fairing assy (1 set) <i>CNE</i>	\$ <i>1280</i> 2,800.00 <i>✓</i>
		\$ 10,163.00
	Less 10%	\$ 1,016.30
		\$ 9,146.70

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Ong Ga Hwa (91263247)

Accident Date : 01-Sep-23

Vehicle No : JTL5352 (DOR: 11062019)

Vehicle Model : Yamaha YZF-R25

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	new 10	\$	38.00	10
2	Fork oils	PA	\$	48.00	X
2	Fork oil seals	PA	\$	100.00	X
1	Bearing cone	PA	\$	120.00	60
1	Engine slider	cut ✓	\$	485.00	280
1	Rear slider	cut ✓	\$	225.00	200
				\$	1,016.00


S/No. Labour

1	To provide towing (LOD) S\$40.00	refer LOD	\$	-	X
2	To check wiring and reset headlamp focusing		\$	80.00	X
3	To re-alignment body frame		\$	550.00	X
4	To provide labour		\$	480.00	380
				\$	1,110.00

Grand Total

\$ 11,272.70

Singapore Dollars: Eleven Thousand Two Hundred Seventy-Two and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5098
102
4588.2
130
380
5518.2
203
4414