



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNN 9890Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	1,785.00	1,785.00
1	REAR BUMPER SIDE HOLDER	NOT NECESSARY	125.00	-
1	REAR BUMPER CENTRE GUIDE	NOT NECESSARY	245.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	763.00	-
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	485.00	-
2	REAR BUMPER SIDE MOULDING @\$152.00	O/S NECESSARY	304.00	152.00
1	REAR BUMPER EXHAUST CHROME PIPE	NOT NECESSARY	445.00	-
1	REAR BUMPER EXHAUST CHROME PIPE BRACKET	NOT NECESSARY	78.00	-
2	REVERSE SENSOR @\$265.00	DAMAGED (1PC ONLY)	530.00	265.00
4	REVERSE SENSOR HOLDER @\$25.00	NECESSARY	100.00	100.00
1	TAILLAMP	CRACKED	765.00	765.00
1	TAILLAMP LOWER BRACKET	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-568.00	-312.20
			5,112.00	2,809.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR WHEEL RIM (SN)	CUT	1,350.00	1,000.00
1	REAR TYRE (SN)	NOT NECESSARY	380.00	-
			1,780.00	1,050.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		600.00	300.00
	SPRAY PAINTING.		600.00	400.00
	WIRING.		50.00	30.00
	TO SPRAY TUFF COAT.		150.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	200.00	-
			1,850.00	810.00
<b>GRAND TOTAL</b>			<b>8,742.00</b>	<b>4,669.80</b>

Report Ref No. CS/AGI24090363/Avp3e2(N)



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,700.00</b>
---	--	--	-----------------

Report Ref No. CS/AGI24090363/Avp3e2(N)

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**