

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24090379/Tgh3e2	
		AY #25-01 NORTH TOWER	Date:	08/10/2024	
	SINGAPORE 04858	3			
_			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 6090R	Veh. Inspected	SMF 9036C	
	Policy No.	- AV (00 4/00 40	Coverage	0	
	Claim No.	AVS24/2846	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	20/09/2024	
2.					
	Make & Model	HYUNDAI ELANTRA	C.C	1591	
	Engine No.	G4FGJU277111	Year of Reg.	29/11/2018	
	Chassis No.	KMHD841CMJU766798	Colour	BLUE	
	Odometer	69308 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65 R15	PIRELLI	6	
	L/H Front Tyre	195/65 R15	PIRELLI	6	
	R/H Rear Tyre	195/65 R15	PIRELLI	6	
	L/H Rear Tyre	195/65 R15	PIRELLI	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	13/09/2024	Inspection Date	23/09/2024	
	Survey held at	6 MARSILING LANE - REPAIRER: CE	NTURY MOTORS (	SINGAPORE) PTE LTD	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days