## **Enquire if Your Vehicle is Under Recall**

## **Vehicle Recall Details**

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE	
	Owner ID Type Singapore NRIC
	Owner ID 553E
	Vehicle No. SML1665H
	Make/Model B.M.W./ 316I 1.6 AT D/AB 4DR ABS HID
	Engine No.: A967J394N13B16A
	Chassis No.: WBA3A12050J719782

## **Recall Details**

## Recall No.: R2024081433

Manufacturer Recall Date:

09 Jul 2024

Estimated Completion Year of Recall:

2027

Brief Description (As Provided by Motor Dealer):

This recall affects vehicles from the Fxx series, which might be equipped with a SDI Takata driver front airbag inflator due to a steering wheel retrofitting from a Basic or Sport to a MSports version.

Date Rectified:

Hotline Information:

PERFORMANCE MOTORS LTD at 1800 2255 269 EUROKARS AUTO PTE LTD at 6219 8388

For more details, contact BMW ASIA PTE LTD