ASS. REC. BY:	0384/Rnp3   560 G
	GNMENT
From: Date:  Estimated Cost:  OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Veh No: SLQ 72417 Yr Regn: Ze (1, July Type: M.Cay / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
To Inspect Vehicle No: SLQ 72417	Make: HONDA HRV 1/5 LX CVT cc 1496  Colour BULL: AC: Insured / Std / NI / NA
al Workshop mis ELICE AWO MOTIVE	Water Comments
or 1 CORPORATION DR FUL-17	Chiragania () 00 3 2
olymos instruction is the state of the state	Eng/No: C/No: JHMRU 18 304 X 2025tl
Policy No.	Gen. Cond: Good // Sic Poor / Burnt
Claims No.	Steering: Inforder & Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)  Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
MONG UI TUIL	Tyre Size: F: 215 Lor 16
(Dallay Carellina)	R: 44
(Policy Condition)  Remark: The weh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Ball or Market Value: 52K	Front / Rear
IDAC Accident Roort: Consistent? : Yes or No	R/Bal. mm R/Bal. a mm
GIA / PR Seen: Consistent?: Yes or No	L/Bai. 1 mm L/Bai. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 76/09/24 D.O.I. 23/09/24
Lum Sum: % 3 Val.: Yes or No	Survey held at CARPGRATION
CA 1 REV   REP. 1 24 HRS  Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or
Date: Person Confacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAIR LYMIT- 29K	· · · · · · · · · · · · · · · · · · ·
	Days Of Repair:
1) Osia/Time, File Relates to?	Resurvey No. of Trip; Survey Fee:
2) Add Fee	An an annual
	: Interview (\$ ) Photos
Report Format:	:Tech, Invs (\$ ) Others
Lump Sum / I.B.I: (\$	:Weekend (\$

the same of the bearing

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number: SLQ7241T

Vehicle Model: HRV 1.5 LX CVT

Chassis Number: JHMRU1830GX202511

**Estimated Repair Cost** 

1 TAIL GATE LAW	S/N	Parts Description	Qty	List Price
2 TAIL GATE LOCK.  3 TAIL GATE WEATHERSTRIP A 1 1 178.20  4 "HRV" EMBLEM A 1 5 33.50  5 "I-VTEC" EMBLEM A 1 5 30.50  6 TAIL LAMP (LH & RH) LH-X (Z 5 1069.20)  7 TAIL GATE LAMP (LH & RH) LH-Y (LH-X 12 5 125.80)  8 TAIL GATE CENTER GARNISH (M 1 5 125.80)  9 TAIL GATE INNER TRIM A 1 5 125.80  9 TAIL GATE INNER TRIM CLIPS A 1 5 1350.10  10 TAIL GATE INNER TRIM CLIPS A 1 5 1350.10  11 TAIL GATE SCREEN INNER SEAL A 1SET 5 97.20  13 TAIL GATE ABSORBER (LH & RH) 2 5 360.40  14 WIPER A 1 5 68.20  15 WIPER BLADE A 1 5 68.20  16 WIPER MOTORY 1 5 68.20  17 REAR BUMPER CLIPS A 1 5 849.50  18 REAR BUMPER CLIPS A 1 5 849.50  19 REAR BUMPER RETAINER (LH & RH) LH-A 1			1	\$ 1100.90
1 \$ 107.80  4 "HRV" EMBLEM A 33.50  5 "I-VTEC" EMBLEM A 1 \$ 30.50  6 TAIL LAMP (LH & RH) LH-CAL   RH-X   (Z \$ 1069.20)  7 TAIL GATE LAMP (LH & RH) LH-SUL   RH-X   (Z \$ 589.20)  8 TAIL GATE LAMP (LH & RH)   RH-SUL   RH-X   (Z \$ 589.20)  10 TAIL GATE LAMP (LH & RH)   RH-SUL   RH-X   (Z \$ 589.20)  11 TAIL GATE INNER TRIM A 1 \$ 185.20  10 TAIL GATE INNER TRIM CLIPS A 1 \$ 185.20  11 TAIL GATE INNER TRIM CLIPS A 1 \$ 1350.10  12 TAIL GATE SCREEN INNER SEAL A 1 \$ 1350.10  13 TAIL GATE ABSORBER (LH & RH)	-		1	\$ 178.20
"HRV" EMBLEM M.   1			1	\$ 107.80
1 \$ 30.50 6 TAIL LAMP (LH & RH) LH-CAL   RH-X			1	\$ 33.50
6 TAIL LAMP (LH & RH) LH-CA / RH-X  7 TAIL GATE LAMP (LH & RH) XLH-SU/RH-X  8 TAIL GATE LAMP (LH & RH) XLH-SU/RH-X  9 TAIL GATE CENTER GARNISH (M 1 \$ 225.80  9 TAIL GATE INNER TRIM M 1 \$ 185.20  10 TAIL GATE INNER TRIM M 1 \$ 185.20  11 TAIL GATE INNER TRIM CLIPS M 1 \$ 1350.10  12 TAIL GATE SCREEN INNER SEAL M 1SET \$ 97.20  13 TAIL GATE ABSORBER (LH & RH)		"I-VTEC" EMBLEM	1	\$ 30.50
TAIL GATE LAMP (LH & RH) & CD-30 (NH X )  TAIL GATE CENTER GARNISH (M		TAIL LAND ILLE DID I HARA / IRH-X	(2	\$ 1069.20
9 TAIL GATE CENTER GARNISH (M) 1 \$ 185.20  10 TAIL GATE INNER TRIM (LIPS M) 15 \$ 75.00  11 TAIL GATE SCREEN INNER SEAL M 1SET \$ 97.20  12 TAIL GATE ABSORBER (LH & RH) 2 \$ 360.40  14 WIPER M  15 WIPER BLADE X 1 \$ 80.60  16 WIPER MOTOR X 1 \$ 68.20  17 REAR BUMPER CLIPS M 1 \$ 849.50  18 REAR BUMPER RETAINER (LH & RH) LH-M 2 \$ 36.40  20 REAR BUMPER REFLECTOR (LH & RH) LH-M 2 \$ 360.40  21 REAR SIDE BUMPER (LH & RH) LH-M 2 \$ 360.40  22 REAR SPLASH SHIELD (LH & RH) LH-M 2 \$ 352.60  23 REAR SPLASH SHIELD CLIPS M 2 \$ 360.40  24 REAR WHEEL ARCH (LH & RH) LH-M 2 \$ 391.20  25 REAR FENDER (LH & RH) LH-M 2 \$ 391.20  26 REAR FENDER INNER TRIM (LH & RH) LH-M 2 \$ 1863.60  27 REAR FENDER INNER TRIM (LH & RH) LH-M 2 \$ 1863.60  28 SPARE TYRE TANK TYPE TANK UPPER BOARD M 1 \$ 225.70		TAIL GATE LAMP (LH & RH) * LH-SU/RH-X		\$ 589.20
1 \$ 185.20  10 TAIL GATE INNER TRIM CLIPS ***  11 TAIL GATE SCREEN ***  11 TAIL GATE SCREEN INNER SEAL ***  12 TAIL GATE SCREEN INNER SEAL ***  13 TAIL GATE ABSORBER (LH & RH)  14 WIPER **  15 WIPER BLADE **  16 WIPER MOTOR **  17 REAR BUMPER MOTOR **  18 REAR BUMPER CLIPS ***  10 \$ 68.20  11 \$ 849.50  12 REAR BUMPER RETAINER (LH & RH) LH-**  10 \$ 50.00  11 PREAR BUMPER RETAINER (LH & RH) LH-**  11 \$ 36.40  12 REAR SIDE BUMPER (LH & RH) LH-**  12 \$ 36.40  24 REAR SIDE BUMPER (LH & RH) LH-**  25 REAR SPLASH SHIELD (LH & RH) LH-**  26 REAR WHEEL ARCH (LH & RH) LH-**  27 REAR SPLASH SHIELD CLIPS ***  30 \$ 150.00  24 REAR WHEEL ARCH (LH & RH) LH-**  25 REAR FENDER INNER TRIM (LH & RH) LH-**  26 REAR FENDER INNER TRIM (LH & RH) LH-**  27 REAR FENDER INNER TRIM (LH & RH) LH-**  28 SPARE TYRE TANK ***  19 SPARE TYRE TANK ***  10 \$ 10 \$ 50.00  10 \$ 10 \$ 50.00  11 \$ 10 \$ 50.00  12 \$ 10 \$ 10 \$ 50.00  13 \$ 10 \$ 10 \$ 50.00  14 \$ 10 \$ 10 \$ 50.00  15 \$ 10 \$ 10 \$ 50.00  16 \$ 10 \$ 10 \$ 50.00  17 \$ 10 \$ 10 \$ 50.00  18 \$ 10 \$ 10 \$ 50.00  29 \$ 10 \$ 10 \$ 10 \$ 10 \$ 10 \$ 10 \$ 10 \$ 1		TAIL GATE CENTER GARNISH (1/2)	1	\$ 225.80
10 TAIL GATE INNER TRIM CLIPS		TAIL GATE INNER TRIM de	1	\$ 185.20
1 S 1350.10  12 TAIL GATE SCREEN INNER SEAL	10		15	\$ 75.00
12 TAIL GATE SCREEN INNER SEAL	11		1	\$ 1350.10
WIPER	12		1SET	\$ 97.20
1 \$ 68.20  16 WIPER MOTOR	13	TAIL GATE ABSORBER (LH & RH)	2	\$ 360.40
1 \$ 265.10  17 REAR BUMPER ALL  18 REAR BUMPER ALL  10 \$ 50.00  19 REAR BUMPER RETAINER (LH & RH) LH-ALL   & H-X   2 \$ 36.40  20 REAR BUMPER REFLECTOR (LH & RH) LH-2   & RH-X   2 \$ 360.40  21 REAR SIDE BUMPER (LH & RH) LH-DL   & RH-X   2 \$ 352.60  22 REAR SPLASH SHIELD (LH & RH) X   2 \$ 267.60  23 REAR SPLASH SHIELD CLIPS 7   30 \$ 150.00  24 REAR WHEEL ARCH (LH & RH) LH-DL   & RH-X   2 \$ 391.20  25 REAR FENDER (LH & RH) LH-DL   & RH-X   2 \$ 1863.60  26 REAR FENDER INNER TRIM (LH & RH) LH-DL   & RH-X   2 \$ 700.80  27 REAR FENDER INNER TRIM CLIPS N   1 \$ 838.30  29 SPARE TYRE TANK PEGAL   1 \$ 838.30  Discount Less   20% \$ 2410.60	14	WIPER ✓	1	\$ 80.60
1 \$ 849.50  18 REAR BUMPER CLIPS AV  10 \$ 50.00  19 REAR BUMPER RETAINER ( LH & RH) LH-AW   EY-X   Z \$ 36.40  20 REAR BUMPER REFLECTOR (LH & RH) LH-?   RH-X   2 \$ 360.40  21 REAR SIDE BUMPER (LH & RH) LH-AW   EH-X   2 \$ 352.60  22 REAR SPLASH SHIELD (LH & RH) X   2 \$ 267.60  23 REAR SPLASH SHIELD CLIPS Y   30 \$ 150.00  24 REAR WHEEL ARCH ( LH & RH) LH-AW   RH-X   Z \$ 391.20  25 REAR FENDER (LH & RH) LH-AW   RH-X   Z \$ 1863.60  26 REAR FENDER INNER TRIM (LH & RH) LH-AW   RH-X   Z \$ 700.80  27 REAR FENDER INNER TRIM (LH & RH) LH-AW   RH-X   Z \$ 150.00  28 SPARE TYRE TANK PYAW   1 \$ 838.30  29 SPARE TYRE TANK UPPER BOARD   1 \$ 225.70  Discount Less   20% \$ 2410.60	15	WIPER BLADE X	1	\$ 68.20
18 REAR BUMPER CLIPS	16		1	\$ 265.10
19 REAR BUMPER RETAINER (LH & RH) LH-ALL   RH-X   2 \$ 36.40  20 REAR BUMPER REFLECTOR (LH & RH) LH-?   RH-X   2 \$ 360.40  21 REAR SIDE BUMPER (LH & RH) LH-OL   RH-X   2 \$ 352.60  22 REAR SPLASH SHIELD (LH & RH) X   2 \$ 267.60  23 REAR SPLASH SHIELD CLIPS   30 \$ 150.00  24 REAR WHEEL ARCH (LH & RH) LH-OL   RH-X   2 \$ 391.20  25 REAR FENDER (LH & RH) LH-OL   RH-X   2 \$ 1863.60  26 REAR FENDER INNER TRIM (LH & RH) LH-OL   RH-X   2 \$ 700.80  27 REAR FENDER INNER TRIM CLIPS   1 \$ 838.30  29 SPARE TYRE TANK PEGAL   1 \$ 225.70  Discount Less   20% \$ 2410.60	17	REAR BUMPER du	1	\$ 849.50
20 REAR BUMPER REPLECTOR (LH & RH) LH- 10 1	18	REAR BUMPER CLIPS A	10	\$ 50.00
20 REAR BUMPER REPLECTOR (LH & RH) LH- 10 1	19	REAR BUMPER RETAINER (LH & RH) LH-ALL/ RY-X	12	\$ 36.40
21 REAR SIDE BUMPER (LH & RH) LH-du / RH-X  22 \$ 352.60  22 REAR SPLASH SHIELD (LH & RH) X  23 REAR SPLASH SHIELD CLIPS 7  30 \$ 150.00  24 REAR WHEEL ARCH (LH & RH) LH-du / RH-X  25 REAR FENDER (LH & RH) LH-du / RH-X  26 REAR FENDER INNER TRIM (LH & RH) LH-du / RH-X  27 REAR FENDER INNER TRIM (LH & RH) LH-du / RH-X  28 352.60  29 \$ 267.60  30 \$ 150.00  20 \$ 391.20  21 \$ 700.80  22 \$ 352.60  23 \$ 267.60  30 \$ 150.00  24 \$ 1863.60  25 \$ 700.80  26 \$ 150.00  27 REAR FENDER INNER TRIM CLIPS AT / ITALIAN STATE IN ST		REAR BUMPER REPLECTOR (LH & RH) LN 107- A	2	\$ 360.40
23 REAR SPLASH SHIELD CLIPS 7  24 REAR WHEEL ARCH ( LH & RH) LH-dL / RH-X  25 REAR FENDER (LH & RH) LH-dL / RH-X  26 REAR FENDER INNER TRIM (LH & RH) LH-dL / RH-X  27 REAR FENDER INNER TRIM CLIPS N  28 SPARE TYRE TANK regar  29 SPARE TYRE TANK UPPER BOARD dL  Discount Less  20% \$ 150.00  \$ 12053.00  Discount Less  20% \$ 2410.60		REAR SIDE BUMPER (LH & RH) LH-d-/ RH-X		\$ 352.60
24 REAR WHEEL ARCH ( LH & RH) LH-L- RH-X  25 REAR FENDER (LH & RH) LH-LH-LRH-X  26 REAR FENDER INNER TRIM (LH & RH) LH-LH-LL-X  27 REAR FENDER INNER TRIM CLIPS A  28 SPARE TYRE TANK regary  29 SPARE TYRE TANK UPPER BOARD L-  Discount Less  20% \$ 12053.00  Discount Less  20% \$ 2410.60			2	\$ 267.60
26 REAR FENDER INNER TRIM (LH & RH) LN-de RH-X   Z		REAR SPLASH SHIELD CLIPS 7	30	\$ 150.00
26 REAR FENDER INNER TRIM (LH & RH) LN-de RH-X   Z		REAR WHEEL ARCH (LH & RH) LH-	12	\$ 391.20
27 REAR FENDER INNER TRIM CLIPS A 150.00 28 SPARE TYRE TANK repair 29 SPARE TYRE TANK UPPER BOARD 2 1 \$ 838.30 29 Discount Less 20% \$ 12053.00  Ligt Prices Tests  Discount Less 20% \$ 2410.60		CARTENDER (LIT & RIT) LH-IMA	12	1863.60
28 SPARE TYRE TANK repair  29 SPARE TYRE TANK UPPER BOARD 21 \$ 838.30  1 \$ 838.30  1 \$ 225.70  Discount Less 20% \$ 2410.60		7 DEAD CENTED OF THE		\$ 700.80
29 SPARE TYRE TANK UPPER BOARD 225.70    S		E COLOR TRIM CLIPS I	5 30	\$ 150.00
Discount Less 20% \$ 2410.60		1	1	838.30
Discount Less 20% \$ 2410.60	-	STAKE THE TANK UPPER BOARD &	1	\$ 225.70
Discount Less 20% \$ 2410.60				\$ 12053.00
Ligt Driver Tetal		Discount Less	20%	
		List Prices Total		

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty		
1 2 3	REAR NUMBER PLATE WITH HOLDER SU / REVERSE SENSORS Shod / WINDSCREEN SEALANT M		\$ \$ \$	50.00 35 450.00 200 35.00
	Special Nett Total		\$	545.00
	Spare Part's Total Price		\$	10187.40

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322 Tel: 6339 7378 Fax: 6339 7475

Vehicle Number: SLQ7241T

Vehicle Model: HRV 1.5 LX CVT

Chassis Number: JHMRU1830GX202511

N	Labour Descriptions	C	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO	\$	1800.00
	CUT & WELD WHERE NECESSARY;TO REPLACE DAMAGED PARTS AS LISTED ABOVE		1500
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR SIDE BUMPER (LH & RH), END PANEL.	\$	1800.00 (20)
3	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$	289.00 150
4	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$	158.00
5	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$	150.00 60
6	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$	150.00 80
1	7 TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$	290.00 YU
8 LABOUR FOR INSTALL REAR WINDSCREEN		\$	150.00 (20
	Labour Tota	\$	4680.00
- 11	Parts & Labour Tota	\$	14867.40
t	Parts & Labour Tota  KK Auto Consultants hence notify ne Repairer of the following: To resurvey before/after spray peinting To display demaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	To display damaged part(s) during resurvey  Parts prices are subject to confirmation	68	
	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed	w	
	Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company	1	
A	cknowledged by Repairer  ignature:  ate:  23   09	120	
	ignature:	1-1	\ <u></u>
Di	Pas alt	VYH	Page 3 of 3

#0.1249L0001 / Elite Am Pte Ltd ENTRY DATE & TIME: 21/09/2024 14:16 (SGT) SUBMITTED BY: Hang Pek Chin VERSION: 1 (21/09/2024 14:18 (SGT))

### SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aloresald.

#### ACCIDENT STATEMENT

Date of First Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

21/09/2024 14:16 (SGT) Both Policyholder and Actual Driver 20/09/2024 13:05 (SGT) Singapore CHOA CHU KANG ROAD Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**SLQ7241T** 

Honda

Private hire

Auto

1496

Hr-V

INBURED/POLICYHOLDER

is company? Name Of Registered Owner NRIC No Email Address Mobile Phone No Alternative Phone No

No LOH ZHENHAO (LUO ZHENHAO) SXXXX560E elite.automotive13@gmail.com (Phone) +65-91884019

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Vehicle Fuel

First Registration Date

Chassis no

Effective Date/Time of Ownership

**HISURANCE COMPANY** 

Name of Insurance Company Policy Number / Cover Note Number

Income Insurance Limited

5138996385-01

No - Claiming third party

CHANGE



Pass Date
Q License Pass Class
Q License Validity
Ing experience
In Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver

LOH ZHENHAO (LUO ZHENHAO) SXXXX560E 12/04/1984 Outdoor 18/03/2004 3

Valid
20 YEARS AND 6 MONTHS

Male (Phone) +65-91884019

elite.automotive13@gmail.com 133B TENGAH GARDEN AVENUE #07-478

S692133 Yes

No

GENERAL INFORMATION OF THE ACCIDENT

Insurance Company of Other Vehicle Owned by Driver

Type of Accident Weather Conditions Road Surface Collision - Head to Rear

Clear Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

No 2 Yes

Yes Yes 1 No -

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes

Jurong East Neighbourhood Police Centre (Phone) +65-18008999999 (Fax) +65-66655791 No. 92 Boon Lay Way Singapore 609962 No

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident

Yes Yes

SD CARD HAS TAKE BY TRAFFIC POLICE

## DETAILS OF OTHER VEHICLE PROPERTY 1

chicle Registration Number GBE4188R

Vehicle Model
Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

NEO SONG HUAT

NRIC No SXXXX263D Contact Number -

Address -

Address complement -

Postcode -

Insurance Company Name

Nature Of Damage -

Details of property damaged in accident

No. Of Passenger (Including Driver)

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person LOH ZHENHAO (LUO ZHENHAO)

Gender Male

Phone No (Phone) +65-91884019

Address 133B TENGAH GARDEN AVENUE #07-478

Address Complement

Post Code S632133

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle? SLQ7241T

Were seat belts worm?

Was this injured conveyed to hospital by ambulance? Yes

SKETCH PLAN

TENTE

Vehicle A: SLQ 72417 value 8: SBE 4186 K

those the long Rad

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ESCRIBE CIRCUMSTANCES OF THE ACCIDENT
while I was writing get the tearffic What Suddently which
B ha fire my vehicle was portion, I was Injuries and
go to hospital by combulance.
"SUPPLIESTANT NOTE: You had been advised by the workshop that in the event that you wish to claim against your own policy (Own Damagnat Claim), from it is FOURTEEN (1A) days clause whereby the claim most be made within the alphabet breathering from the day of occurrence.
A LTD A Count of a Chairm of athers workshop (COVTR)

| | Reporting Only | | Own Damage | | Third Party | | Claim at other workshop (DON'T

DECLARATION

I/We declare the for going particulars are true in every res

Policy State of State

Oriver's Signature
(If driver is not the policyholder
Gate & Time:

Reporting Centre Personnel's Signature Name

### > Back to OneMotoring

### **Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	560E
/ehicle Details	
Vehicle No.:	SLQ7241T
Vehicle to be Exported:	No
ntended Deregistration Date:	23 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	L15B4532510
Chassis No.:	JHMRU1830GX202511
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,197.00
Original Registration Date:	20 Jul 2017
First Registration Date:	20 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$18,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2027
PARF Rebate Amount:	\$10,845.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$12,072.00
Total Rebate Amount:	\$22,917.00
Message	rrent COE (including unused COE from any lay-up period/s), if you renew your COI

The information contained herein is correct as at 23 Sep 2024

### m.sgcarmart.com













### Honda HR-V 1.5A LX


**\$52,000** Instalment \$1,178/mth

PREMIUM AD



**BuySafe** 















#### Overview Financial Photo Research

(i) 2017

Depreciation

(i) \$15,180 / year

Reg. Date

24-Jul-2017 (2yrs 10mths COE left)

Manufactured

84,500 km (11.8k / year)

Mileage

Auto

View specs of the Honda HR-V

Transmission

1,496 cc

**Engine Cap** Road Tax

(i) \$682 / year

Power

96.0 kW (128 bhp)

(2015-2021)

Curb Weight

① 1,190 kg

COE

\$42,801

View car via BuySafe