

(08/11/13) waf

ASS. REC. BY:

REF: CS/SMR 24090385/Rvp3

2009

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLQ 2249E

at Workshop m/s BORNBU

of PANDAN CRESCENT

Insured: SMB 1475S-SMR

Policy No. _____

Claims No. BUS/09/24/5047


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 58k

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 40k

Veh No: SLQ 2249E Yr Regn: 7017 / JUN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 18CVT c.c. 1798

Colour: Grey AC: Insured / Std / NI / NA

Sp. Reading: 541660 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YTDKBS3FU603561848

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS (DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/09/24

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 23/09/24

PANDAN C

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

11/10/24. Rasul confirmed final fig \$16,619.40 (red 19,892.40, 54%)



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 23/09/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU603561848		2ZRS057165	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	B	BP-LAB2 CHECK WIRING SYSTEM				198.00	
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00	
4	B	BP-LAB2 REMOVE INTERIOR UPSTOPRY TO FAC REPAIR				396 792.00	
5	B	BP-LAB2 REMOVE AND TRANSFER REAR & FRONT DOOR CO MPARTMENT				X 792.00	
6	B	BP-MECH2 CONDUCT WHEEL ALIGHTMENT				198.00	
7	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				3168 452.00	
8	B	BP-RES2 RESPRAY ACC AFF AREA				3936 5248.00	
9	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SMRT BUS ACC DATE:21/09/24 DRIVE IN:21/09/24 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50.	
10	1	U52159-47913 COVER, RR BUMPER <i>repm</i>	1.00	680.60		680.60	
11	2	U52576-47040 RETAINER, RR BUMPER X	1.00	177.50		177.50	
12	3	U52592-47040 SEAL, RR BUMPER X	1.00	122.30		122.30	
13	4	U52453-47010 GUARD, RR BUMPER, X	1.00	884.60		884.60	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			23/09/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDBK3FU603561848	2ZRS057165	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	5	U52566-47900 FILLER, RR BUMPER X	1.00	170.50		170.50
15	6	K52161-0K040 PIECE, RR BUMPER X	10.00	5.80		58.00
16	7	U61602-47160 PANEL SUB-ASSY, repair	1.00	1339.40		1339.40
17	8	U58746-47030 PROTECTOR, QUARTER	1.00	31.90		31.90
18	9	T08826-08115 PANEL BONDING AD X	1.00	267.20		267.20
19	0	U67004-47211 PANEL SUB-ASSY, RR repair	1.00	1988.60		1988.60
20	1	U67872-47051 WEATHERSTRIP, RR X	1.00	249.10		249.10
21	2	U75978-47080 STRIPE, RR DOOR, X	1.00	30.40		30.40
22	3	U75988-47060 STRIPE, RR DOOR, X	1.00	48.50		48.50
23	4	U75989-47070 STRIPE, RR DOOR, X	1.00	21.40		21.40
24	5	U67002-47163 PANEL SUB-ASSY, FR repair	1.00	1996.10		1996.10
25	6	U67862-47050 WEATHERSTRIP, FR X	1.00	320.90		320.90
26	7	U75976-47060 STRIPE, FR DOOR, X	1.00	18.50		18.50
27	8	U75986-47050 STRIPE, FR DOOR, X	1.00	60.40		60.40
28	9	U75966-47030 STRIPE, FR DOOR X	1.00	36.60		36.60
29	0	L90269-04051 RIVET X	20.00	2.20		44.00
30	1	T90269-06013 RIVET X	20.00	2.80		56.00
31	2	U53802-47100 FENDER SUB-ASSY, FR bt	1.00	1488.90		1488.90
32	3	U53828-47070 PROTECTOR, FR FENDER ?	1.00	129.90		129.90
33	4	U53808-47020 SEAL SUB-ASSY, ?	1.00	72.00		72.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 23/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q3	30/06/2017	SLQ2249E	0	33202	75/DS/SLQ2249E	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU603561848		2ZRS057165	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
34	5	U53155-47010 SEAL, RADIATOR ?			1.00	58.30		58.30
35	6	U53876-47110 LINER, FR FENDER, LH <i>de</i>			1.00	308.70		308.70
36	7	U52119-47962 COVER, FR BUMPER <i>repair</i>			1.00	799.30		799.30
37	8	K52161-0K040 PIECE, RR BUMPER <i>repair</i>			10.00	5.80		58.00
38	9	U52115-47050 SUPPORT, FR BUMPER X			1.00	121.30		121.30
39	0	U52116-47050 SUPPORT, FR BUMPER X			1.00	121.30		121.30
40	1	U53112-47240 GRILLE, RADIATOR, X			1.00	237.60		237.60
41	2	U81145-47691 UNIT, HEADLAMP X			1.00	4063.00		4063.00
42	3	U81145-47691 UNIT, HEADLAMP ?			1.00	4063.00		4063.00
43	4	U81220-47020 LAMP ASSY, FOG, LH X			1.00	1449.90		1449.90
44	5	U75374-47150 EMBLEM, SIDE PANEL <i>as</i>			1.00	75.70		75.70
45	6	U42602-47181 CAP SUB-ASSY, WHEEL <i>scr</i>			2.00	293.60		587.20

Resur
Hp 900ml
8 days
23/09/24
Regr by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Customer's Signature
Please acknowledge receipt of vehicle
Signature: _____

Charge Summary		Total	
Parts	22,236.60		34,612.60
Labour	12,376.00		
Sublet	0.00		
Lubrication/Fluid	0.00		
Others	0.00		
		GST 9.00%	3,115.13
		Less	0.00
		Amount Due	37,727.73

Customer Copy

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLQ2249E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZRS057165
Chassis No.:	JTDKB3FU603561848
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Jun 2017
First Registration Date:	30 Jun 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2027
PARF Rebate Amount:	\$3,000.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$14,692.00
Total Rebate Amount:	\$17,692.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Sep 2024

OK