

**COMPLETE VMS PTE LTD**

5, Soon Lee Street, #01-54, Singapore 627607
(Tel) 6555 6111 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

Muhammad Razik Ariff Bin Bahari
437, Jurong West Avenue 1, #09-422
Singapore 640437

Attention: Owner
Contact: 91689551

ESTIMATE ES 012319
Date 24/9/2024
Vehicle Number SBA5252C
Make / Model CHEVROLET ORLANDO 1.4AT TURBO
Engine Number B14NET170070294
Chassis Number KL1YA7589HK613618
Accident Date 20 Sep 2024
Policy Number

Description	Qty	Unit Price	Amount
-------------	-----	------------	--------

Parts**List Items**

Front Door R/H <i>repair</i>	3097.11	1	S\$1,842.30	S\$1,658.07 <i>XR</i>
Rear Door R/H <i>bt</i>	10%	1	S\$2,136.70	S\$1,923.03
Rear Door Outer Moulding R/H <i>de</i>	2787.39	1	S\$367.81	S\$331.03
Rear Door Window Motor R/H <i>Xenn</i>		1	S\$571.30	S\$514.17 <i>X</i>
Rear Door Window Regulator R/H <i>Xenn</i>		1	S\$516.20	S\$464.58 <i>X</i>
Side Skirt R/H <i>sa</i>		1	S\$592.60	S\$533.34
Rear Fender R/H <i>Xenn</i>		1	S\$1,843.60	S\$1,659.24 <i>X</i>
Rear Fender Outer Moulding R/H <i>Xenn</i>		1	S\$377.30	S\$339.57 <i>X</i>
Rear Wheel Bearing R/H <i>Xenn</i>		1	S\$382.60	S\$344.34 <i>X</i>
Rear Door Frame RH <i>repair</i>		1	S\$2,352.30	S\$2,117.07 <i>XR</i>
Discount 10% applied				\$9,884.44

Special Nett Items

R/H Rear Rims <i>Xenn</i>	40	1	S\$1,376.20	S\$1,376.20
Clip <i>Xenn</i>		10	S\$7.50	S\$75.00 <i>Xo</i>
				\$1,451.20

Labour

Computer Wheel Alignment <i>Xenn</i>	1	S\$120.00	S\$120.00 <i>X</i>
Rust Proofing	1	S\$120.00	S\$120.00 <i>Xo</i>
Spray Paint All Affected Area	600 <i>Xo</i>	S\$1,200.00	S\$1,200.00 <i>Xo</i>
To Remove & Reinstall All Damaged Parts and Facilitate Repair	500	S\$1,200.00	S\$1,200.00

Pages 1 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Muhammad Razik Ariff Bin Bahari
437, Jurong West Avenue 1, #09-422
Singapore 640437

Attention: Owner
Contact: 91689551

COMPLETE VMS PTE LTD
5, Soon Lee Street, #01-54, Singapore 627607
(Tel) 6555 6111 (Fax) 6554 0012 (Web) www.completevms.com.sg
The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE

Date 24/9/2024
Vehicle Number SBA5252C
Make / Model CHEVROLET ORLANDO 1.4AT TURBO
Engine Number B14NET170070294
Chassis Number KL1YA7589HK613618
Accident_Date 20 Sep 2024
Policy Number

Description	Qty	Unit Price	Amount
Remove And Reinstall Door Mechanism To Facilitate Repair	60	S\$180.00	S\$180.00
			\$2,820.00

(200)

Total \$14,155.64

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Razik
Hp 9001068

4 days

L/S

25/09/24

2787.39

40.00

1200.00

34027.39

209

3271.91

L/S - \$3,200 / 4 days

Res after
requr

Pages

2 / 2

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin