

**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**






**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**






**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**






**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**






**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**







**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**






**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**








**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**








**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**INSPECTION PHOTOS (Page 20 of 20)**

### PHOTOGRAPHS FOR VEHICLE NO. : SLZ 9779Z

