



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24060176/Uqh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	21/06/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 5279J	Veh. Inspected	SMH 1157D
Policy No.	-	Coverage	0
Claim No.	IVS24/1175	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	20/06/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS HYBRID (A)	C.C	1797
Engine No.	2ZR2B83599	Year of Reg.	11/01/2019
Chassis No.	ZVW506149921	Colour	BLUE
Odometer	449966 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	DUNLOP	6
L/H Front Tyre	195/65R15	DUNLOP	6
R/H Rear Tyre	195/65R15	DUNLOP	6
L/H Rear Tyre	195/65R15	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/06/2024	Inspection Date	21/06/2024
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days