10/8/24, 3:36 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090399/EQP3M4

Date: 08/10/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAA00605 **Claimant Vehicle SHA3136Y Insured Vehicle No:** SNR7043U

No:

Date of Loss: 23/09/2024 Nature of Claim: ΤP Claim No: M2405483

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHA3136Y Reg No:

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A) Engine No: G4LEKU408599 Chassis No: KMHC851CVLU189801 Reg. Date: 30/09/2020 (Man. Year: 2019)

Colour: Blue Odometer: 434883 km

Engine Capacity: 1580 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Footbrake (Serviceable): Yes Yes Pre-accident Condition: Good Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,106.68	2,106.68	0.00	0.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,780.00	1,240.00	540.00	30.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,898.68	3,358.68	540.00	13.85
Approved Total (Overridden) (S\$))	2,700.00		
(S\$)	3,898.68	2,700.00	1,198.68	30.75
+ GST 9.00/9.00% (S\$)	350.88	243.00	107.88	30.75
Nett Amount (S\$)	4,249.56	2,943.00	1,306.56	30.75

INSPECTION

Date of Assignment: 24/09/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

COMFORTDELGRO ENGINEERING PTE LTD

Date Inspected: 24/09/2024 Inspected At: 59 LOYANG DRIVE

SINGAPORE 508969

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2024)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA3136Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,797.20 FL	*1,797.20 FL
2	1		*FRONT DOOR PROTECTOR RH	Cut	186.20 FL	*186.20 FL
3	1		*REAR DOOR PROTECTOR RH	Cut	166.20 FL	*166.20 FL
4	1		*FRONT DOOR (COMFORTDELGRO) RH	Necessary	75.00 F	*75.00 F
5	1		*REAR DOOR (ZIG) APPS RH	Necessary	80.00 F	*80.00 F
<u>Sup</u>	<u>pleme</u>	entary #1				
6	1		*ROCKER PANEL GARNISH RH	Deformed	290.00 FL	*290.00 FL
F=Fra	nchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	2,594.60	2,594.60
			- List Item Discount on L Iter	ns 20.00/20.00% (S\$)	487.92	487.92
				Total Parts (S\$)	2,106.68	2,106.68
			Report was unsubmitted during t	his print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cella	neous Items			,
1	1	OD/TP Case (Insurer)		12.00	12.00
			Sub Total (S\$)	12.00	12.00
					,

Recommended Labour

Recommended Edition					
No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	PANEL BEATING (REAR DOOR RH ETC)	New	800.00	380.00	
2	SPRAY PAINTING	New	600.00	560.00	
3	TUFF KOTE	New	80.00	20.00	
<u>Sup</u>	plementary #1				
<u>Lab</u>	<u>our Items</u>				
4	SPRAY PAINTING	New	300.00	280.00	
		Gross Labour Cost (S\$)	1,780.00	1,240.00	
		Report was unsubmitted during this print-out.			

< END OF ESTIMATES >