

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Mohamed Albasa Ir Mohamed
Siddiq (88932952)

Accident Date :

Vehicle No : FBT1435T (COE: 151121-141131)

Vehicle Model : Yamaha Xmax
300 ABS CVT

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Footstep panels - R/H	\$ 225.00 ✓
1	Exhaust protector	\$ 125.00 ✓
1	Rear footrest - R/H	\$ 125.00 ✓
1	Rear footrest bracket - R/H	\$ 380.00 ✓
1	Rear cover	\$ 285.00 ✓
1	Footstep lower cover	\$ 145.00 ✓
1	Center cover	\$ 220.00 ✓
		\$ 1,505.00
Less 10%		\$ 150.50
		\$ 1,354.50
<u>Special Net Items</u>		
1	"X MAX" emblem	\$ 120.00 ✓
		\$ 120.00
<u>Labour</u>		
1	To provide towing service (LOD)	\$ -
2	To check wiring and reset headlamp focusing	\$ -
3	To provide labour	\$ 380.00 100
4	To repair body frame	\$ -
		\$ 380.00
Grand Total		\$ 1,854.50

Singapore Dollars: One Thousand Eight Hundred Fifty-Four and Cents: Fifty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Page 1 of 1

Date:

P- 880
102
792
60
100
952
20
761.