

SAFE AUTO

Reg No:
Blk 25 kaki bukit road 4 #05-83 S(417800)
Mobile no: 97777040
Email : safeauto88@hotmail.com

Xiao Chen.

24 September 2024

QUOTATION FOR ACCIDENT REPAIR OF SMC9427Z HYUNDAI ACCENT THIRD PARTY INSURER: LIBERTY

<u>S/No.</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear boot lid <i>Repair</i>	1	\$ 907.00 <i>+</i>
2.	Rear boot lid Logo emblem <i>Green</i>	1	\$ 65.00 <i>✓</i>
3.	Rear boot lid Accent emblem <i>Green</i>	1	\$ 68.00 <i>✓</i>
4.	Rear boot lid weather strip <i>Green</i>	1	\$ 155.00 <i>+</i>
5.	Rear boot lid mechanism lock <i>Green</i>	1	\$ 175.00 <i>+</i>
6.	Rear taillamp L/R <i>ut</i>	2	\$ 1060.00 <i>@ 430</i>
7.	Rear bumper <i>Deformed</i>	1	\$ 553.00 <i>✓</i>
8.	Rear bumper side reflector lamp <i>new</i>	2	\$ 156.00 <i>+</i>
9.	Rear bumper reinforcement <i>cracked</i>	1	\$ 428.00 <i>✓</i>
10.	Rear bumper reinforcement bracket <i>Deformed</i>	4	\$ 220.00 <i>80.</i>
11.	Rear end panel <i>Dented</i>	1	\$ 455.00 <i>✓</i>
12.	Rear end panel garnish <i>Deformed</i>	1	\$ 162.00 <i>✓</i>
Subtotal before discount			\$ 4404.00
Discount 20%			\$ 880.80
Subtotal 1			\$ 3523.20
<u>S/Nett.</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear bumper clip <i>new</i>	1	\$ 30.00 <i>✓</i>
2.	Rear bumper reverse sensor (4pcs) <i>new</i>	1	\$ 450.00 <i>X</i>
3.	rear end panel garnish clip <i>new</i>	1	\$ 30.00 <i>20.</i>
S/Nett Total			\$ 510.00

Rear Labour

To check wiring and rectify electrical faults where necessary	\$ 60	30
To remove and refit rear fender inner trims and attachment to facilitate the repairs.	\$ 150	60
To remove and replace reverse sensors and check/program sensing distance	\$ 120	50
To straighten, repair, realign on front affected area and replace damaged parts	\$ 1000	700
To spray painting on affected area	\$ 1000	700

Total Labour Cost \$ 2330

total: 3702.80
h/s: 2950.
05 Days.

Liberty Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: