



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090412/Uqh3
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	10/10/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 4969L	Veh. Inspected	YN 6466E
Policy No.	-	Coverage	0
Claim No.	AVS24/2947	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	24/09/2024

2. Vehicle Details

Make & Model	mitsubishi fuso fm65fm2rdeb	C.C	7545
Engine No.	6M60191521	Year of Reg.	10/10/2014
Chassis No.	FM65FMA10099	Colour	WHITE
Odometer	376405 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80R22.5	NEW POWER	6
L/H Front Tyre	295/80R22.5	NEW POWER	6
R/H Rear Tyre	295/80R22.5 (D)	KUNLUN	6/6
L/H Rear Tyre	295/80R22.5 (D)	KUNLUN	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/09/2024	Inspection Date	24/09/2024
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days