

(08/11/13) wef
ASS. REC. BY:

REF: CS/AIG 24090418/Rvp3

5500

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SLC 7709K
at Workshop m/s PREMIUM
of Peru Secur
Insured: AIG
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: TBA
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 85K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC 7709K Yr Regn: 2016 / Jun
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Audi Q7 2.0 FFSI Qu c.c. 1984
Colour: GREY AC: Insured / Std / NI / NA
Sp. Reading: 110535 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: WAV 2224M 140064854

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/45R20
R: 1

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>23/09/24</u>		D.O.I. <u>25/09/24</u>

Survey held at Peru

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair L.M.T-32K

Date/Time, File Pass to?

☐
☐

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

1) Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0720/2024/KS
DATE : 25-Sep-24
WIP : 32111

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/09/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. CHRISTOPHER CHONG CHI CHUIN
ADDRESS : 17 HOLLAND PARK
SINGAPORE 247707
TELEPHONE : HP +65 91912288
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100471730-07
VEHICLE NO : **SLC 7709 K**
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 22/6/2016
ENGINE NO : CYR 015333
CHASSIS NO : WAUZZZ4M1GD064854
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Sep-24
PLACE OF ACCIDENT : 23 ANGULLIA PARK GROUND FLOOR LOBBY



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 7709 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	S/N \$ 280.00	X
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00	/
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	?
4	TO REMOVE AND RENEW LHS ADDITIONAL RADIATOR.	S/N \$ 880.00	/
5	TO CARRY OUT VACUUM AND REGAS R1234.	S/N \$ 1,200.00	/
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	600
7	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,800.00	1900
8	TO RENEW LHS FRONT RIM WITH TYRE AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	280
8	TO CARRY OUT FRONT CAMERA CALIBRATION AND ADAPTATION.	S/N \$ 480.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		: \$ 11,082.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 7709 K.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>from ✓</i>	1	\$ 3,254.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 503.00	
3	FRONT BUMPER AIR GUIDE <i>cm ✓</i>	1	\$ 84.00	
4	FRONT BUMPER CLOSING - UPPER CENTRE <i>?</i>	1	\$ 347.00	
5	FRONT BUMPER GRILLE <i>?</i>	1	\$ 258.00	
6	FRONT BUMPER UNDERRUN BAR <i>?</i>	1	\$ 1,011.00	
7	FRONT BUMPER CLOSING ELEMENT <i>cm ✓</i>	1	\$ 263.00	
8	FRONT BUMPER SPOILER - LH / RH <i>X</i>	2	\$ 526.00	
9	RADIATOR GRILLE <i>?</i>	1	\$ 3,039.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>mis ✓</i>	1	\$ 374.00	
11	FRONT PARKING AID SENSOR <i>mis ✓</i>	1	\$ 286.00	
12	FRONT PARKING AID SENSOR SEAL RING <i>cm ✓</i>	4	\$ 11.00	
13	FRONT BUMPER WIRING SET <i>X</i>	1	\$ 751.00	
14	LED HEADLIGHT - LH <i>?</i>	1	\$ 11,979.00	
15	LIFT CYLINDER - LH <i>cm ✓</i>	1	\$ 238.00	
16	LIFT CYLINDER HOSE - LH <i>cm ✓</i>	1	\$ 124.00	
17	FRONT FENDER - LH <i>ref ✓</i>	1	\$ 2,043.00	
18	FRONT FENDER ATTACHMENT PARTS - LH <i>X</i>	1	\$ 138.00	
19	FRONT FENDER BRACKET - LH <i>X</i>	1	\$ 76.00	
20	FRONT FENDER BRACKET - LH <i>X</i>	1	\$ 80.00	
SUB TOTAL SPARE PARTS		:	\$ 25,385.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 7709 K.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE - LH X	1	\$	210.00
22	FRONT WHEEL HOUSING LINER - LH <i>turn</i>	1	\$	289.00
23	FRONT WHEEL HOUSING LINER ATTACHMENT - LH X	1	\$	206.00
24	FRONT WHEEL SPOILER - LH OUTER <i>cm</i>	1	\$	55.00
25	FRONT WHEEL SPOILER - LH INNER <i>cm</i>	1	\$	72.00
26	FRONT WHEEL ARCH COVER - LH / RH <i>m</i>	2	\$	1,548.00
27	ADDITIONAL RADIATOR <i>bt</i>	1	\$	1,076.00
28	ADDITIONAL RADIATOR BRACKET <i>m</i>	1	\$	170.00
29	ADDITIONAL RADIATOR AIR GUIDE <i>cm</i>	1	\$	62.00
30	RADIATOR COOLANT <i>m</i>	6	\$	332.00
31	REFRIGENT LINE <i>bt</i>	1	\$	392.00
32	REFRIGENT LINE <i>bt</i>	1	\$	281.00
33	REFRIGENT LINE X	1	\$	341.00
34	HORN X	1	\$	270.00
35	FRONT NO PLATE X	S/N	\$	60.00
36	FRONT RIM - LHS <i>cut</i>	1		PRICE TBA
37	FRONT TYRE - LHS <i>cut</i>	1	\$	520.00
38	SUNDRIES ?		\$	600.00
TOTAL SPARE PARTS		:	\$	31,869.00
TOTAL LABOUR CHARGES		:	\$	11,082.00
GRAND TOTAL		:	\$	42,951.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Rasul - Hp 90010268

SURVEYED DATE

: 25/09/24

AUTHORISED DATE

: 5 days

EXCESS COST

: Repair

LIABILITY

: EXCESS : TBA

REMARKS

: Repair by paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	550D
Vehicle Details	
Vehicle No.:	SLC7709K
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2024
Vehicle Make:	AUDI
Vehicle Model:	Q7 2.0 TFSI QU (252 BHP)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CYR015333
Chassis No.:	WAUZZZ4M1GD064854
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$58,999.00
Original Registration Date:	22 Jun 2016
First Registration Date:	22 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$78,199.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2026
PARF Rebate Amount:	\$43,009.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$9,735.00
Total Rebate Amount:	\$52,744.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 26 Sep 2024

OK



Audi Q7 2.0A TFSI Quattro Panoramic Roof 7-Seater

\$98,000 Instalment \$2,780/mth

 This car is eligible for [Sgcarmart Warranty](#)

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$24,910 / year
Reg. Date	30-Dec-2016 (2yrs 3mths 3days COE left)
Manufactured	 2016
Mileage	97,988 km (12.7k / year)
Transmission	Auto
Engine Cap	1,984 cc
Road Tax	 \$1,194 / year
Power	185.0 kW (248 bhp) View specs of the Audi Q7 (2015-2022)
Curb Weight	 2,050 kg
COE	 \$54,901
OMV	 \$61,968