

ESTIMATE

Name: India International Insurance Pte Ltd

Ref Date:

23/09/2024

Address: Motor Claims Department

Ref No:

GBL647Y240920

64 Cecil Street #04-00 & #05-00

Vehicle No:

GBL647Y

IOB Building

Singapore 049711

Model / Make:

Toyota Hiace

Capacity: 2982 cc

Van Turbo 4 DR AT

[illegible]

not Audited
merant
24/9/24
2/5 \$ 7400
take 90% after exp -
10 days.





Liu's Brother Auto Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN & GST No: 42674600K

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: India International Insurance Pte Ltd

Ref Date:

23/09/2024

Address: Motor Claims Department

Ref No:

GBL647Y240920

64 Cecil Street #04-00 & #05-00

Vehicle No:

GBL647Y

IOB Building

Singapore 049711

Model / Make:

Toyota Hiace

Capacity: 2982 cc

Van Turbo 4 DR AT

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
		B/F Balance --->			\$ 13,196.10		
27		Rear Tailgate "Corporate" Advertisement & Artwork			\$ 450.00	SN	ren 200 S/W
28		Rear Fender "Corporate" Advertisement & Artwork			\$ 680.00	SN	ren 350 S/W
29		To check all wiring & electrical component for proper function			\$ 50.00		20
30		Remove and refix rear bumper reverse sensor			\$ 80.00		3.2
31		Remove & reinstall Tailgate Windscreen Glass to facilitate repairs			\$ 120.00		100
32		Remove and refix rear tailgate components & mechanism			\$ 100.00		50
33		Remove and replace rear exhaust pipe system to facilitate repairs			\$ 100.00		mx
34		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,800.00		1200
35		To putty & spray painting & including touch up paint on accident affected areas			\$ 1,500.00		900
36		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 100.00		80

Total Parts & Labour of estimate for damaged vehicle	Sub-Total
--	-----------

\$ 18,176.10

Total amount in Lumpsum Basis for repaired vehicle	
GST TAX	9.00%

\$ 1,635.85

Grand Total

\$ 19,811.95

SDL



Liu's Brother Auto Workshop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5- 8161.7
 25%
 6171.28
 840
 2380
 9341.28
 202
 7473