



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090424/Unh3e2
75 BRAS BASAH ROAD	Date:	17/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBV 7562J	Veh. Inspected	SNA 5253H
Policy No.	-	Coverage	0
Claim No.	MT/1296401-002	Excess	\$0.00
Assign From	JULIE	Assign Date	24/09/2024

### 2. Vehicle Details

Make & Model	MERCEDES BENZ E200 (A)	C.C	1991
Engine No.	26492030423107	Year of Reg.	28/06/2021
Chassis No.	W1K2130802A980332	Colour	BLUE
Odometer	14935 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R18	PIRELLI	6
L/H Front Tyre	245/45R18	PIRELLI	6
R/H Rear Tyre	245/45R18	PIRELLI	6
L/H Rear Tyre	245/45R18	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION, FRONT BONNET AND ROOFTOP.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	20/09/2024	Inspection Date	07/10/2024 (10:10)
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days