

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709634

Date : 20/09/2024

Vehicle Num. : SKQ227T

Make/Model : HONDA CIVIC

Chassis/Eng# : MRHFC5650JT001570

Accident Date : 20/09/2024

Claim No. :

Reference :

Policy No. :

S/N Quantity Particular Unit Price Amount S\$

LIST ITEMS :			
1.	1PC	N/S HEADLAMP <i>one</i>	708.80 908.00
2.	1PC	N/S HEADLAMP CHROME <i>one</i>	103.60 173.00
3.	1PC	N/S HEADLAMP LOWER BRACKET <i>one</i>	91.40 141.00
4.	1PC	RADIATOR GRILLE <i>one</i>	189.00 X
5.	1PC	RADIATOR GRILLE LOGO <i>one</i>	45.00 X
6.	1PC	FRONT BUMPER <i>one</i>	579.90 779.00
7.	1PC	N/S FRONT BUMPER SIDE RETAINER <i>one</i>	35.00
8.	1PC	N/S FRONT BUMPER AIR GRILLE <i>one</i>	93.00
9.	1PC	N/S FRONT FENDER <i>one</i>	450.80 650.00
10.	1PC	N/S FRONT FENDER INNER SHIELD <i>one</i>	131.00
11.	1PC	N/S FRONT FENDER LAMP <i>one</i>	118.00
12.	1PC	N/S WING MIRROR <i>one</i>	60.00 467.00
13.	1PC	N/S WING MIRROR LAMP <i>completed</i>	307.90 135.00 X
14.	1PC	N/S WING MIRROR COVER <i>one</i>	99.00
15.	1PC	N/S FRONT DOOR GLASS <i>one</i>	349.30 549.00
16.	1PC	N/S FRONT DOOR GLASS MOULDING - OUTER <i>one</i>	75.80 145.00
17.	1PC	N/S REAR DOOR <i>one</i>	949.20 1,077.00
18.	1PC	N/S REAR DOOR TAPE <i>one</i>	60.00 92.00
19.	1PC	N/S REAR DOOR HINGE - TOP <i>one</i>	96.00 X
20.	1PC	N/S REAR DOOR HINGE - BOTTOM <i>one</i>	96.00 X
21.	1PC	N/S REAR DOOR CHECKER <i>one</i>	126.00 X
22.	1PC	N/S REAR DOOR REGULATOR GEAR <i>one</i>	253.00 X

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709634

Date : 20/09/2024
Vehicle Num. : SKQ227T
Make/Model : HONDA CIVIC
Chassis/Eng# : MRHFC5650JT001570
Accident Date : 20/09/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	N/S REAR DOOR REGULATOR MOTOR <i>11 X</i>		268.00 <i>X</i>
24.	1PC	N/S SIDE SKIRT <i>247</i>		260.00 <i>X</i>
25.	1 PC	FRONT BUMPER <i>reinforcement 50/341</i>	<i>418.60</i>	618.00 <i>X</i>
List TotalS\$:				7,543.00
20.00% Discount S\$:				1,508.60
				6,034.40 <i>s/n</i>
SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP <i>11 X</i>		40.00 <i>30</i>
2.	1SET	FRONT BUMPER RIVET <i>11 X</i>		60.00 <i>X</i>
3.	1SET	N/S FRONT FENDER INNER SHIELD CLIP <i>11 X</i>		40.00 <i>30</i>
4.	1SET	N/S SIDE SKIRT CLIPS <i>11 X</i>		40.00 <i>30</i>
5.	1 PC	N/S FRONT FENDER BODY SEALANT <i>11 X</i>		80.00 <i>X</i>
6.	1 PC	N/S FRONT DOOR BODY SEALANT <i>11 X</i>		80.00 <i>X</i>
Special Nett Total S\$:				340.00
LABOUR :				
TO FOCUS HEADLAMP & WIRING <i>20</i>				50.00 <i>20</i>
TO TRANSFER DOOR GLASS <i>3</i>				120.00 <i>50</i>
TO TRANSFER DOOR MECHANISM <i>3</i>				120.00 <i>50</i>
TO RUSTPROOF ON DAMAGED PARTS <i>60</i>				250.00 <i>80</i>

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709634

Date : 20/09/2024

Vehicle Num. : SKQ227T

Make/Model : HONDA CIVIC

Chassis/Eng# : MRHFC5650JT001570

Accident Date : 20/09/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO APPLY BODY SEALANT ON BODY JOINTS	12 X	250.00 X
		TO RESET POWER WINDOW	11 X	250.00 X
		TO RESET DOOR CENTRAL LOCKING USING DIAGNOSTIC SCANNER	11 X	250.00 X
		TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	600	1,200.00 600
		TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	1100	1,500.00 1100
		Labour Total S\$:		3,990.00

E. & O.E.

Total S\$: 10,364.40

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-47733
202

3818.64

90

1835

5758.64

22

4606