

Damage assessment report:

16th Aug 2024

Mr. Goh Mia Song

IC: S0020806Z

HP: 97853282

Bike: Willier Zero 9 Carbon

The abovementioned Bicycle is found damaged/scratched and out of alignment, deemed unsafe to be used in future, and it is beyond repair. Total amount is \$7675.00
The breakdown below,

1. Frameset - \$2600.00 / DEF
2. Groupset: Campagnolo Chorus 11 - \$2250.00 / BT
3. Wheelset: Campagnolo Shamal Ultra - \$1400.00 / BT
4. Pedal: Look Keo 2 Max Carbon Blade - \$205.00 / CUT
5. Cockpit: FSA K-Wing Carbon bar, Stem - \$450.00 / BT
6. Saddle: Astute Carbon - \$290.00 / BT
7. Tires: Vittoria Corsa - \$160.00 / CUT
8. Specialized S-Work Helmet - \$320.00 / BR

- 10% depreciation

Best Regards,

Ben Cheong

Chapter 2 Cycle Pte Ltd

UEN: 201103127M

451, Ang Mo Kio Ave 10

#01-1761, Singapore 560451

Tel: 64527168



Steve (LKK)
26/9/24, 9.30 am
with Prejudice
2 days
P/P

Bik 451, Ang Mo Kio Ave 10 #01-1761

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: