

*Athina Kannath*  
**Cheng Hoe Motor Pte Ltd**

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

*SKW9443U*  
*TP/FC*

M/S : MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

TEL: 65073848 FAX: 65073849  
ATTN: Motor Claim Department

WS Ref: TP FC  
Claim Type: Third Party  
Accident Date: 21/09/2024  
TP Veh Reg No: SHC3313S

*Not Authored*  
*11 Sur & 3600p*  
*Repair After Pain*  
*4 days*

Estimate No: ES2400794/WS  
Date: 24 Sep 2024  
Policy No:  
Veh Reg No: SKW9443U  
Make/Model: TOYOTA TOYOTA CAMRY 2.0  
Chassis No: MR053DK5100104663  
Engine No:  
Reg. Date: 23/11/2015

**Estimate Repair Cost to Vehicle No :SKW9443U**

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 FRONT BUMPER	917.90	1 PC	917.90	—
2 FRONT BUMPER LH SIDE RETAINER	153.50	1 PC	153.50	—
3 FRONT BUMPER LH CORNAL PARKING SENSOR	555.20	1 PC	555.20	—
4 FRONT BUMPER CLIP	4.50	6 PC	27.00	—
5 FRONT BUMPER LH QUARTER GARNISH	84.10	1 PC	84.10	— X
6 HEADLAMP LH	1,807.30	1 PC	1,807.30	—
7 FRONT LH FENDER EMBLEM 'VVTI'	70.60	1 PC	70.60	—
8 FRONT LH FENDER	1,318.90	1 PC	1,318.90	—
			4,934.50	
		Less 25%	1,233.63	3,700.88
<b>Labour</b>				
9 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT LH FENDER;TO KNOCKING & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	400.00	1 LA	400.00	—
10 PUTTY & RESPRAY ON FRT BUMPER,FRT LH FENDER,FRT SUPPORT PANEL	600.00	1 LA	600.00	500
			1,000.00	1,000.00
		Total	S\$ 4,700.88	
		Add GST @ 9%	423.08	
		Total Amount Payable	S\$ 5,123.96	

*Parts \$4850.40*  
*25%*  
*1212.60*  
*\$3637.80*  
*900*  
*\$4537.80*  
*\$31600p*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**For Cheng Hoe Motor Pte Ltd**

AUTHORISED SIGNATURE