

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Muhammad Haziq Bin Azmi (94596634)**

Accident Date : **15-Sep-24**

Vehicle No : **FBN4580T (COE: 081018-071028)**

Vehicle Model : **Yamaha Sniper T150**

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy <i>n</i>	\$ 640.00 <i>x</i>
1	Fork under bracket <i>su</i>	\$ 225.00 <i>x</i>
1	Front fender bracket <i>n</i>	\$ 125.00 <i>x</i>
1	Front side cover (matt) - 1 set <i>cu7</i>	\$ 145.00 <i>✓</i>
1	Front wheel rim <i>nn</i>	\$ 580.00 <i>x</i>
1	Front rim shaft <i>cu7</i>	\$ <i>50</i> 115.00 <i>✓</i>
1	Front rim bearing <i>su</i>	\$ 90.00 <i>x</i>
1	Front brake disc <i>nn</i>	\$ 235.00 <i>x</i>
1	Handle bar <i>nn</i>	\$ 185.00 <i>x</i>
1	Handle-bar end (1 set) <i>nn</i>	\$ 155.00 <i>x</i>
1	Hand grip (1 set) <i>nn</i>	\$ 85.00 <i>x</i>
1	Front signal (1 set) <i>cu</i>	\$ <i>40</i> 140.00 <i>✓</i>
1	Pilot lights <i>cu</i>	\$ <i>185</i> 380.00 <i>✓</i>
1	Front horn inner cover centre matt black <i>cu</i>	\$ 125.00 <i>✓</i>
1	Front horn inner cover <i>m.s</i>	\$ <i>40</i> 185.00 <i>✓</i>
1	Fairing assy (1 set) <i>cu</i>	\$ 1500 680.00 <i>✓</i>
1		\$ <i>480</i> 4,245.00
Less 10%		\$ 424.50
		\$ 3,820.50

Special Net Items

	Number plate (1 set) <i>nn</i>	50.00 <i>x</i>
1	Fork oils <i>nn</i>	\$ 38.00 <i>x</i>
2 1	Fork oil seals <i>nn</i>	\$ 30.00 <i>x</i>
2 1	Steering cone (1 set) <i>nn</i>	\$ 56.00 <i>x</i>
1	Sticker set <i>nn</i>	\$ 180.00 <i>120</i>
1		\$
		\$

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Muhammad Haziq Bin Azmi (94596634)**

Accident Date : **15-Sep-24**

Vehicle No : **FBN4580T (COE: 081018-071028)**

Vehicle Model : **Yamaha Sniper T150**

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>			
	To provide towing service (LOD)			
1	To check wiring and reset headlamp focusing	refer LOD	\$	- X
2	To repair body frame		\$	17 80.00 X
3	To provide labour		\$	17 480.00 X
4			\$	40.00 - 200
			\$	1,040.00
Grand Total			\$	5,284.50

Singapore Dollars: Five Thousand Two Hundred Eighty-Four and Cents: Fifty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1245
102
112050
120
200
1440.5
213
1152