

YEW HOK AUTO SERVICES

522 Bedok North Ave 1, #11-310, Singapore 460522

H/P: 8285 7623

Email: yhlee@outlook.sg

Not Authorized
du
Merang
25/9/24
2/s \$7500/
Whaphertharper
7 days

Vehicle number: SKR4426D

Vehicle Made & Model: MERCEDES-BENZ CLA 180

Qty	List Items	Amount \$
1	Rear bumper DO/Torn 1484.32	1,698.61 ✓
1	Rear bumper difusser Jntd	551.43 ✓
1	Rear bumper chrome moulding Cnt	211.42 ✓
2	Rear bumper PDC sensors @ 313.75 Svc	627.50 x
1	Rear bumper top guide Tm1	161.90 ✓
2	Rear bumper side guides - L/R @ 110.25 nn	220.50 x
2	Rear bumper side retainers - L/R @ 110.25 nn	220.50 x
1	Rear bumper reinforcement Bnt 715.32	1,075.60 ✓
1	Rear end panel DO	941.60 ✓
1	Rear end panel garnish Svc	180.93 x
2	Rear exhaust chrome trims - L/R @ 441.50 Svc	883.00 x
2	Rear taillamps - L/R @ 841.63 nn	1,683.26 x
1	Front bumper D.S	1,731.78 ✓
1	Front bumper badge Nm	87.63 ✓
1	Front bumper tow cover ms	75.53 ✓
1	Front bumper grille - CTR Tm1	191.63 ✓
2	Front bumper side grilles - L/R @ 81.50 nn	163.00 x
2	Front bumper PDC sensors @ 313.75 nn	627.50 x
1	Front bumper top guide support Tm1	431.59 ✓
1	Front bumper top plate Cnt	151.65 ✓
1	Front bumper top seal Nm	121.30 ✓
1	Front bumper sponge Torn	180.93 ✓
1	Front bumper reinforcement Bnt	871.60 ✓
1	Front grille assy Cnt	1,238.78 ✓
2	Front headlamps - L/R @ 3139.88 holder Cnt	6,279.76 ✓
2	Front headlamp control units - L/R @ 851.65 nn	1,703.30 x
1	Air intercooler Pm1	1,251.60 ✓
1	Air con condenser Bnt	1,240.36 ✓
1	Radiator Svc	1,290.63 x
Sub-total		26,094.82
Less 10%		2,609.48
Total List		23,485.34

Vehicle number: SKR4426D

Vehicle Made & Model: MERCEDES-BENZ CLA 180

Special Nett Items

1 set	Rear bumper clip	AM	50.00	30
1 set	Front bumper clip	AM	50.00	30
1 set	Front no. plate	Scp2	80.00	40
1 bot	A/C oil	AM	65.00	30
1 bot	Radiator coolant	AM	65.00	x
Total Special Nett			310.00	

Labour charges

To check front/rear electrical wiring	80.00	30
To remove, refix rear interior trims to assist repair	120.00	60
To remove, refix A/C condenser & refill A/C gas	180.00	100
To diagnose, erase fault memory after repair	AM 350.00	x
To respray undercoating	150.00	40
To respray painting and etc	1,800.00	1000
Panel beating, cut, weld remove & replacing above parts	1,600.00	1000
Total Labour	4,280.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 28,075.34

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Page 2 of 2 Date: