## **Veron Chen (LKKAuto)**

From:

Zac Law Qi Zhi <zaclaw@vinsautogroup.com.sg>

Sent:

Monday, 7 October 2024 3:07 PM

To:

Veron Chen (LKKAuto)

Cc:

Vin's Claims; Sharon Tan Chow Yen

Subject:

Re: SNN6129J - ECICS OD - DOA: 20/9/2024 - ENGINE OIL LEAK

**Attachments:** 

ENGINE OIL LEAK (5).jpeg; ENGINE OIL LEAK (1).jpeg; ENGINE OIL LEAK (1).mp4;

ENGINE OIL LEAK (2).jpeg; ENGINE OIL LEAK (2).mp4; ENGINE OIL LEAK (3).jpeg;

ENGINE OIL LEAK (4).jpeg

## Good afternoon,

There is an issue of engine oil leak for SNN6129J. Owner stated that the engine oil leak issue was caused by accident. Kindly advice.

Best Regards, Zac Law Claims Consultant Vin's Automotive Group Omotenashi | Kaizen OI's denous of the Bit hear body how to affect the enjine. The leakage of the enjine is due to new & tear.



M: 9163 7828

O: 6453 2121 Ext: 2206

F: 6459 0433

E: zaclaw@vinsautogroup.com.sg

W: https://vinsautogroup.com.sg/

From: Zac Law Qi Zhi <zaclaw@vinsautogroup.com.sg>

Sent: Friday, October 4, 2024 1:32 PM

To: Sharon Tan Chow Yen <sharon\_tan@ecics.com.sg>
Cc: Vin's Claims <claims@vinsautogroup.com.sg>

Subject: SNN6129J - ECICS OD - DOA: 20/9/2024 - ENGINE OIL LEAK

## Good afternoon,

There is an issue of engine oil leak for SNN6129J. Owner stated that the engine oil leak issue was caused by accident. Kindly advice.

Best Regards,
Zac Law
Claims Consultant
Vin's Automotive Group
Omotenashi | Kaizen