

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automobile	
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24090465/Evh3e2	
	ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583		Date:	11/12/2024	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBM 5725S	Veh. Inspected	SNR 7378D	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/2969	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	25/09/2024	
2.		Vehi	cle Details		
	Make & Model	TOYOTA NOAH	C.C	1797	
	Engine No.	2ZR2V71304	Year of Reg.	01/07/2024	
	Chassis No.	ZWR900113232	Colour	WHITE	
	Odometer	23040 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55 R17	YOKOHAMA	7	
	L/H Front Tyre	205/55 R17	YOKOHAMA	7	
	R/H Rear Tyre	205/55 R17	YOKOHAMA	7	
	L/H Rear Tyre	205/55 R17	YOKOHAMA	7	
4. Description of Damages					
THE	VEHICLE SUSTAII	NED DAMAGES AT THE REAR POR	TION.		
DAN	MAGES SEE DETAII	_S.			
5.	General Information				
	Accident Date	24/09/2024	Inspection Date	26/09/2024	
	Survey held at 8 KAKI BUKIT AVE 4 #08-19 PREMIER @ KAKI BUKIT S415875 - REPAIRER: MIRAI AL PERFORMANCE PTE LTD				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
				REPAIRS.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days