	CS/CTI24090467/Kqh3
	SIGNMENT
From: Date:	Veh No: SMR 2815D Yr Regn: 01, 16
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD htp iws/tp res/od res/eva/inv/my	Truck / Trailer or A)
To Inspect Vehicle No:	Make: Porsche Cayenges 2967
at Workshop m/s Ding	Colour M. P. White AC: Insured / Std / NI / NA
	Sp.Reading /6/394 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: WP17778927GKA46136
Sum Insured: Excess: 2/C	Gen. Cond: Geod' Fair / Poor / Burnt
(Client's Record)	Steering: Inorder/ Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / ST& A/Rim or
	Tyre Size: F; 275/45R20
(Policy Condition)	R: 2737 43 1720
Pomark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PER / SUM/
repair at the time of inspection.	ТОУО / УОКО ог
Bal, or Market Value: \$\Beta\05/C	Front n Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. of mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. / mm L/Bal. 5 mm
Est. Repairs: Ob days Res.: Yes or No	D.O.A. 22/9/24 D.O.I. 27/9/202
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages Fit Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
1/4 1/4 5 1/4 1/4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	400000000000000000000000000000000000000
Kenneth finalised LS \$25550 (Red	L\$23988.32, 48%)
	The second secon
	And a service of the department of the control of t
•	and the second distribution of the second distri
	The second secon
: Prell. Report	Days Of Repair: 6
05/12 Typist : Final Report	Resurvey No. of Trip: 2 Survey Fee:
uta/lime, File Return to?	Transportation
Add Fee:	The state of the s
Add F89:	The second of th
140°00	: Interview (\$), Finds
port Format: EZCLAIMS-OD	Tech Invs (\$), Ohers
n p Sum / I.B.I: (\$ 25550 1	Weekend (\$
F 00111 - 11011	AAGGVGIIO (A

Full Report

Registration: SMR2815D Printed: 24/09/2024 4:11 PM

Insurer Reference:

Repairer Reference: 072967

Date calculated: 24/09/2024 4:10 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

2 2

!6 !2 !2 !2

32 30

10

98

76

20

82 80

40

.24

.06

.18

3.12

7/1

S

Printed by:

Claim Reference: Estimated Repair Time: Actual Repair Days:

Ding Auto

Currency: Date of Incident: SGD

6day,

Hire Car Start: Hire Car End:

22/09/24

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer:

Model Specs

FROM MODEL 2016 ADDITIONAL HEATING PARKING HELP SYSTEM MULTI FUNC S-WHEEL ST/STEEL SILL TRIM

8-SPEED AUTOMATIC TYRES 265/50 YR 19

TIPTRONIC

PORSCHE

CAYENNE (TYPE 92A)

DIESEL 04 22 10

SMR2815D

WP1ZZZ92ZGKA46136

166594

D/MIRROR WITH MEMORY DOOR POWER CLOSING LEATHER SEAT COVER **EQUIPMENT START/STOP DIPPING AUTOM MIRROR AUTO TAILGATE CONTR**

SERVOTRONIC

WHEELS 8.5J X 19 ALU TWO COAT METALLIC

RADIO PORSCHE CDR31 DRIVER'S MEMORY PACK LANE CHANGING ASSIST

3.0 LTR 190/193KW SUSPENSION COMFORT INTERIOR LAMP PACK PREPARE OFF VEHICLE

SCR SYSTEM **BI-XENON HEADLAMPS COMFORT SEATS DEACTIVATED P/AIRBAG EMISSION STD EURO 6** TYRE PRESSURE SENSOR

NON-SMOKER PACKAGE

Labour

Code	Time Base 10 WU/h	Price = 42.00 SGD/h
Code	Description	WU Price SGD
NO NUMBER	RENEW FRONT NUMBER PLATE	1.0 4.20
63 15 19 00	R + R FRONT SECTION TRIM	12.8 53.76
63 15 55 50	RENEW FRONT PANEL (REMOVED)	20.8 87.3 6
	INCLUDES: R + R AIR VENT GRILLE, NUMBER PLATE BRACKET AND AIR INLET COVER FRAME	
63 10 19 50	REMOVE AND REFIT FRONT BUMPER CARRIER (FRONT BUMPER REMOVED)	6.3 26.46
63 10 55 50)	RENEW FRONT BUMPER SUPPORT (REMOVED)	
50 56 19 01)	DETACH + REFIT FRONT WHEELHOUSE LINER	0.9 3.71
50 56 19 02)	DETACH + REFIT FRONT WHEELHOUSE LINER	1.0 4.20
59 51 19 51)	R + R FRONT AIRBAG SENSOR	1.0 4.2
4 15 20 00	R + R BOTH HEADLAMPS	0.9 3.7 2.4 10.0

Code	Description		WU	Price SGD
50 38 55 70	RENEW FRONT LOCK CARRIER		18.4	77.28
55 22 55 00	RENEW BONNET		12.6	52.92
55 25 20 50	RENEW BOTH FRONT BONNET HINGES (BONNET REMOVED)		6.6	27.72
EE 14 30 00)	R + R BONNET LOCK CABLE	Oberta State His	5.3	22.26
55 14 20 00) 94 14 19 01)		40 KOO - 100 COO	1.6	6.72
94 14 19 01)			1.6	6.72
50 41 55 51	RENEW L/F WHEELHOUSE SUPPORT (COMP WORK)	30000740855555 110040 2*180 0 9400	12.6	52.92
50 41 55 52	RENEW R/F WHEELHOUSE SUPPORT (COMP WORK)	Residence of	12.6	52.92
68 05 19 02)		Washington States of the Control of	1.5	6.30
97 85 09 50	R + R BATTERIE GROUND STRAP	Andre State	0.5	2.10
70 16 19 02	R + R R/INSTRUMENT PANEL COVER	SALTURNOS AT SURVINISMENTAL VINE	1.9	7.98
24 25 19 72	R + R AIR CLEANER		2.8	11.76
NO NUMBER	R + R LOWER CHARGE AIR COOLING PIPE		1.0	4.20
19 24 19 50)	R + R RADIATOR AIR GUIDE	Service of the Contract of	7.1	29,82
87 50 19 70	R + R CONDENSER	ONES A PER SERVICE A PRODUCTION CLASS	4.0	16.80
19 70 19 05)	R + R RADIATOR		7.0	29.40
	INCLUDES: DRAIN + REFILL COOLANT			
19 70 19 05)	R + RADIATOR ADD WORK		12.2	51.24
19 20 19 05)	R + R ELECTRIC FAN		4.3	18.06
87 03 17 50	DRAIN AND REFILL AIR CONDITIONING		7.9	33.18
	REFRIGERANT			
	INCLUDES: CHECK WITH LEAK DETECTOR,			
	CHECK AIR CONDITIONING COOLING			
	Labour Cost	Hrs	w	J
	Panel / Mechanical Labour	16.90	168.	6 708.12
	Total of Labour			708.12

Paint Work		Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	wu	Price SGD
63 15 61 51	FRONT BUMPER NEW PART PAINTING S1	17.0	71.40
63 15 61 71	L/F BUMPER CAP PAINTING	2.0	8.40
55 22 61 51	BONNET NEW PART PAINTING S1	25.0	105.00
55 25 61 51	LEFT BONNET HINGE NEW PART PAINTING S1	3.0	12.60
55 25 61 51	RIGHT BONNET HINGE NEW PART PAINTING S1	3.0	12.60
50 41 61 01	L/F HEADLAMP BRACKET NEW PART PAINTING S1	1.0	4.20
50 41 61 01	R/F HEADLAMP BRACKET NEW PART PAINTING S1	1.0	4.20
01 75 61 51	PAINT FRONT PARKING AID SENSOR/S	1.0	4.2
1 01 71 11	PREPARATION FOR PAINTING NEW PART S1 (PART/S FITTED)	19.0	79.8
1 01 71 21	PREPARATION FOR PAINTING (COMPOSITE WORK)(PART FITTED)	5.0	21.0
1 01 71 25	PREPAINT FRONT LID (REMOVED) S1 COMPOSITE WORK	4.0	16.8

Total Paint Hrs WU Price SGD 8.10 81.0 340.20

Spare Parts

prices as at 2001-01-01

Code	Description	Part Number	Part Source	Price SGD
0471	BONNET	958 511 01110GR	V Original	by 5,800.00 —
0503	BONNET CABLE	958 511 53111	Original	/*\ 150.00 \(\chi \)
1000	BONNET DAMPER LHS	BONNET DMPR LH		200.00 ×
1001	BONNET DAMPER RHS	BONNET DMPR RH		LECTION AND THE SECTION OF THE SECTION OF THE SECTION AND THE SECTION OF THE SECT
0481	BONNET INSULATION	958 556 83120	Original	12 400.00 Y
0493	BONNET LOCK	958 511 50902 958 511 48001	Original Original	74 150.00 ×
0494 0524	BONNET SAFETY LATCH BONNET SEAL	958 511 61101	Original	5 300.00 X
4465	CONDENSER	958 573 11102	Original	2,800.00 7
7772	CONDENSER FIX FRAME		Original	800.00 7
8778	CONDENSER FRAME	958 575 29100	Original	800.00 2
7789	ELECTRIC FAN CPL	958 106 06120	Original	Bilim 2,600.00 -
0283	FRONT BUMPER	958 505 21707G2		
0431	FRONT MANUFACT BADGE	958 559 60102	Original	
0257	FRONT NUMBER PLATE	KNPL3	Original	70.00 45/~
0347	FRT BUMPER FILLING	958 505 55020	Original	<i>cm</i> 308.00 ←
0340	FRT BUMPER SUPPORT	958 505 10901	Original	2,500.00
0930	FRT LOCK CARRIER	958 505 59402	Original	1,000.00
8770	FRT SOUND INSULATION		Original	650.00 7
0299	GRILLE	958 505 68302	Original	<i>CM</i> 400.00 <i>✓</i> 550.00 ×
9650	HIGH TONE HORN	958 635 10705	Original	950.00 ^
0637	L/ADD DRIVING LAMP	958 631 18131	Original	650.00 7
7449	L/F ACCELERAT SENSOR		Original	300.00 7
0313	L/F BRAKE AIR GUIDE	958 505 79510	Original	250.00 7
0291	L/F BUMPER AIR GUIDE	958 505 15540G	DY Original	150.00
0293 0343	L/F BUMPER CAP L/F BUMPER GUIDE	958 505 04901	Original	80.00
0303	L/F CENTRE SENSOR	500 919 275B G2		350.00 7
0643	L/F FOG LAMP	955 631 16300	Original	³ ⊷ 550.00 ×
1169	L/F HEADLAMP BRACKET			³ 400.00 ⊀
0355	L/F LWR BUMP LAMINA	958 505 6854591	39 Original	1 300.00 ⊀
0397	L/FOG LAMP COVER	958 505 823009		A- 350.00 X
0297	L/F OUT BUMP GRILLE	958 505 681409		230,00
0301	L/F OUTER SENSOR	5Q0 919 275B G		330.00
0295	L/F WATER DEFLECTOR	958 505 24510	Original	230,00
0361	L/GRILLE MOULDING	958 505 94500	Original	230.00
0341	L/GUIDE	958 505 17750	Original	400,00 7
8631	L/HEADLAMP MOUNTING	958 631 52101	Original	350.00 7
0555	L/HEADLAMP SEAL	958 631 11900	Original	120,00
0475	LEFT BONNET HINGE	958 511 30110	Original	
0561	LEFT HEADLAMP ASSY	958 631 17541	Original	
0638	R/ADD DRIVING LAMP	958 631 18231	Original	
0314	R/F BRAKE AIR GUIDE	958 505 79610	Original	
0292	R/F BUMPER AIR GUIDE	958 505 334459		250.00 7 80.00 7
0344	R/F BUMPER GUIDE	958 505 05001	Original	
0304	R/F CENTRE SENSOR	5Q0 919 275B G	32X Original	220,00
0644	R/F FOG LAMP	955 631 16300	Original	
1170	R/F HEADLAMP BRACKET	7958 501 072000	RV Original	400.00 7
0356	R/F LWR BUMP LAMINA	958 505 686459	B9 Original	300.00 7
AND ADDRESS OF THE PARTY OF THE	R/FOG LAMP COVER	958 505 824009		/2 350.00×
0398	R/F OUT BUMP GRILLE	958 505 682409		250.00 7
0298	R/F OUTER SENSOR	5Q0 919 275B 0	32X Original	5 350.00 ×
0302		958 505 24610	Original	250.00 7
1296	R/F WATER DEFLECTOR	958 505 94600	Original	250.00 7
362	R/GRILLE MOULDING	936 303 94000	Virginia	The state of the s

· .	Description	Part Number	Part Source	Price SGD
Code	R/HEADLAMP MOUNTING		Original	<i>l</i> ← 350.00 ^X
0632	R/HEADLAMP MOUNTING	958 631 12000	Original	120.00 7
0556	R/HEADLAMP SEAL			2,200,00 7
7761	RADIATOR	958 106 13210	Original	
8777	RADIATOR AIR GUIDE	958 575 32331	Original	700.00 7
0929	REAR SUPPORT PART	958 505 93140	Original	350.00 7
	RIGHT BONNET HINGE	958 511 30210	Original	/ 250.00 ×
0476		958 505 17850	Original	400.00 7
0342	RIGHT GUIDE	958 631 17641	Original	3,500.00 7
0562	RIGHT HEADLAMP ASSY			250.00 X
9641	TEMPERATURE SENSOR	958 505 53500	Original	
0933	UP LOCK CARRIER TRIM	958 556 806209B9		450.00 7
0391	UPPER FRONT SPOILER		Original	Dis/1,600.00
	lowe			0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			46,170.00
u: Used parts	Total			46,170.00

Final Calculation

i mai calcalation		
	SGD	SGD
Parts	46,170.00	
Total Parts		46,170.00
Labour Time Base 10 WU/h Total 168.6 WU X 42.00 SGD/h Total of Labour	708.12	708.12
Paint Work Time Base 10 WU/h Labour Cost 81.0 WU X 42.00 SGD/h Fotal Paint Including Material	340.20	340.20
Repair Cost Excludes GST		47,218.32
GST (+9.00%)		4,249.65 51,467.97
Repair Cost Included GST		31,407.37

Comments
* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SD08249N0001 / Ding Auto Pte Ltd ENTRY DATE & TIME: 23/09/2024 11:08 (SGT) SUBMITTED BY: Ding Auto - Claims Dept VERSION: 1 (23/09/2024 11:08 (SGT))

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided triust be as infuling and acceptance of policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission Reported by Date of Accident Exact Location of Accident **Additional Location Information** Country/State of Loss

23/09/2024 11:08 (SGT) Both Policyholder and Actual Driver 22/09/2024 16:50 (SGT) Singapore AFTER ADAM PARK, TOWARDS LORNIE ROAD Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMR2815D

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Fmail Address

LEE XIANG WEI, ALEX NRIC No SXXXX355Z alexleexwcanbefound@gmail.com (Phone) +65-97511706 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC Vehicle Fuel First Regisration Date Chassis no

Effective Date/Time of Ownership

Porsche Cayenne

Private use

Yes Private car Auto 2967 Diesel 21/01/2016

WP1ZZZ92ZGKA46136 26/03/2024 00:00 (SGT)

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number China Taiping Insurance (Singapore) Pte. Ltd. DMPCSNW00034822400

DRIVER



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

4

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

SPC Hadam Park

SMR2815D SMR3290L Unknown vehicle

Jam break,

exit

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour: Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

Singapore NRIC

355Z

SMR2815D

23 Sep 2024

PORSCHE

CAYENNE DIESEL (E2-II) TIP E6

White

2015

034436

WP1ZZZ92ZGKA46136

193.0 kW (258 bhp)

\$84,873.00

21 Jan 2016

21 Jan 2016

3

\$124,772.00

Yes

20 Jan 2026

\$68,624.00

20 Jan 2026

B - Car above 1600cc or 97kW (130bhp)

10

\$57,501.00

\$7,620.00

\$76,244.00

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. The information contained herein is correct as at 23 Sep 2024