

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Vehicle No:

SMZ7788Z

Brand & Model:

Cayenne

Date:

6-Nov-24

Franchise:

PORSCHE

Email/Fax No:

Contact No:

Chassis/VIN No:

WP1ZZZ9YZRDA03046

Contact Person (Eurokars):

FAIZ

Type of Claim:

THIRD PARTY

YEAR MODEL:

02/04/2024

WIP#:

12644

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER RH	P9Y0-807-418- -G2X	1		-	\$ 2,594.60
2	REAR BUMPER LOWER SPOILER	P9Y0-807-543-H -OK1	1		\$ 1,615.50	\$ 1,615.50
3	REAR BUMPER LOWER TRIM	P9Y0-807-834-AL-OK1	1		\$ 1,143.00	\$ 1,143.00
4	EXHAUST TRIM LH	P9Y0-807-837-A -OK1	1		\$ 183.70	\$ 183.70
5	EXHAUST TRIM RH	P9Y0-807-838-A -OK1	1		\$ 183.70	\$ 183.70
6	SUPPORT SHIELD LH	P9Y0-825-715- -	1		\$ 69.10	\$ 69.10
7	SUPPORT SHIELD RH	P9Y0-825-716- -	1		\$ 69.10	\$ 69.10
8	REAR BUMPER SOUND ABSORBER RH	P9Y0-807-248- -	1		-	\$ 114.20
9	SPOILER SOUND ABSORBER LH	P9Y0-807-573- -	1		\$ 71.60	\$ 71.60
10	SPOILER SOUND ABSORBER RH	P9Y0-807-574- -	1		\$ 71.60	\$ 71.60
11	SENSOR GASKET	P5Q0-919-133- -9B9	4		\$ 15.60	\$ 15.60
12	CLAMP	P9Y0-423-337- -	4		\$ 23.20	\$ 23.20
13	EXPANSION RIVET	PPAF-038-549- -	4		\$ 3.20	\$ 3.20
14	BLIND RIVET	PN -908-550-01-	8		\$ 18.40	\$ 18.40
15	EXPANDER NUT	PWHT-004-935- -	4		\$ 8.00	\$ 8.00
16	REAR BUMPER CENTER BRACKET	P9Y0-807-863-A -	1		-	\$ 214.50
17	REAR BUMPER RETAINER RH	P9Y0-807-406-E -	1		-	\$ 104.70
18	REAR BUMPER BRACKET RH	P9Y0-807-376-A -	1		-	\$ 150.10
19	EXPANDER NUT	PN -106-213-01-	9		-	\$ 24.30
20	REAR BUMPER REINFORCEMENT	P9Y0-807-309-D -	1		-	\$ 1,646.80
21	CROSS MEMBER FOR REINFORCEMENT	P9Y0-807-235-A -	1		-	\$ 145.10
22	GASKET LH REINFORCEMENT	P9Y0-807-669- -	1		-	\$ 15.40
23	GASKET RH REINFORCEMENT	P9Y0-807-670- -	1		-	\$ 15.40
24	COVER LOWER END	P9Y0-807-587-A -	1		-	\$ 279.10
25	LOGO CAYENNE	P9Y0-853-670- -LI0	1		\$ 450.90	\$ 450.90
26	TAIL PIPE RH	P9Y0-253-824- -	1		\$ 929.40	\$ 929.40
27	TRIM PANEL FOR CAMERA REAR	P9Y0-807-644-B -OK1	1		-	\$ 168.00

Sub-Total (Parts Price) **\$ 4,856.00** \$ 10,328.20

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER RH, REAR BUMPER LOWER SPOILER & TRIM, REINFORCEMENT & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR TAILGATE & ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,720.00	\$ 5,160.00

2	TO RESPRAY REAR BUMPER RH, TAILGATE	\$ 1,800.00	\$ 2,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 250.00
4	TO SUPPLY REAR LICENCE PLATE WITH CASING	\$ -	\$ 70.00
5	TO TRANSFER THE REVERSE SENSORS.	\$ 250.00	\$ 500.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
8	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days: 4 Days	Excess:
---------------------	----------------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$ 4,540.00	\$ 9,680.00
	REVISED	PRICE
Parts Price	\$ 4,856.00	\$ 10,328.20
Labour Price	\$ 4,540.00	\$ 9,680.00
Total (Initial Estimate)	\$ 9,396.00	\$ 20,008.20
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 9,396.00	\$ 20,008.20
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 9,396.00	\$ 20,008.20
GST 9%	\$ 845.64	\$ 1,800.74
GRAND TOTAL	\$ 10,241.64	\$ 21,808.94