



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24090486/Rnh3m4
300 BEACH ROAD	Date:	28/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	YP 6714D
Policy No.	Z24VC05025251	Coverage	0
Claim No.	24/24/24/VC05/029880	Excess	\$700.00
Assign From	ERIC	Assign Date	27/09/2024

2. Vehicle Details

Make & Model	HINO XZU710R-HKFM53	C.C	4009
Engine No.	N04CUS30655	Year of Reg.	07/07/2017
Chassis No.	JHHUCS3H30K019584	Colour	WHITE
Odometer	493912 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	7.00R16	HAIDA	7
L/H Front Tyre	7.00R16	HAIDA	7
R/H Rear Tyre	7.00R16 (D)	HAIDA	7/7
L/H Rear Tyre	7.00R16 (D)	HAIDA	7/7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2024	Inspection Date	27/09/2024
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE MARKET VALUE IS S\$49,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days