

ESTIMATE

27/9/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: YP6714D
Vehicle Model: CBMQ24090195
Est No:
Claims ref:
Accident Date: 16/09/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	FRONT WINDSCREEN <i>cm</i>	1	PC \$ 780.00	\$ 780.00
2	WIPER ARM LH/RH <i>sa</i>	2	PC \$ 120.00	\$ 240.00
3	WIPER ARM CAP LH/RH <i>sun/mis</i>	2	PC \$ 20.00	\$ 40.00
4	WIPER BLADE <i>X</i>	2	PC \$ 15.00	\$ 30.00
5	FRONT PANEL <i>st</i>	1	PC \$ 580.00	\$ 580.00
6	CORNER PANEL LH/RH <i>LH-cm/RH-X</i>	2	PC \$ 280.00	\$ 560.00
7	CORNER PANEL CAP LH/RH <i>mis</i>	1	PC \$ 35.00	\$ 35.00
8	MIRROR STAY LH <i>st</i>	1	PC \$ 250.00	\$ 250.00
9	MIRROR STAY CAP LH/RH <i>cm/mis</i>	2	PC \$ 35.00	\$ 70.00
10	GRILLE <i>cm</i>	1	PC \$ 430.00	\$ 430.00
11	GRILLE CLIPS <i>m</i>	10	PC \$ 2.50	\$ 25.00
12	HINO LOGO <i>m</i>	1	PC \$ 100.00	\$ 100.00
13	HEADLAMP LH/RH <i>cm</i>	2	PC \$ 550.00	\$ 1,100.00
14	FRONT BUMPER <i>st</i>	1	PC \$ 400.00	\$ 400.00
15	FRONT BUMPER BRKT LH/RH <i>H</i>	2	PC \$ 170.00	\$ 340.00
16	FRONT BUMPER STAY UPPER / LOWER <i>X</i>	2	PC \$ 80.00	\$ 160.00
17	FOG LAMP LH/RH <i>X</i>	2	PC \$ 240.00	\$ 480.00
18	DOOR PANEL LH <i>repair</i>	1	PC \$ 920.00	\$ 920.00
19	616 DECAL <i>m</i>	1	PC \$ 65.00	\$ 65.00
20	EURO 5 EMBLEM <i>m</i>	1	PC \$ 75.00	\$ 75.00
21	STEP GARNISH LH/RH <i>LH-cm/RH-X</i>	2	PC \$ 240.00	\$ 480.00
22	A/C BLOWER ?	1	PC \$ 750.00	\$ 750.00
23	A/C HEATER (CHECK) ?	1	PC	\$ -
24	A/C HEATER PIPE <i>st</i>	2	PC \$ 75.00	\$ 150.00
25	A/C PIPE <i>st</i>	2	PC \$ 220.00	\$ 440.00
26	CABIN BRKT RH <i>st</i>	1	PC \$ 360.00	\$ 360.00
27	CABIN SWING ARM <i>st</i>	1	PC \$ 1,000.00	\$ 1,000.00
28	HORN <i>X</i>	1	PC \$ 85.00	\$ 85.00
29	DASH PANEL (REPAIR)	1	PC	\$ -
30	CHASSIS CROSSMEMBER <i>repair</i>	1	PC \$ 600.00	\$ 600.00

COST TOTAL S\$

15% COST PLUS S\$

\$ 10,545.00

\$ 1,581.75

\$ 12,126.75

SPECIAL NET ITEMS:

1	W/SCREEN PRIMER <i>m</i>	1	PC \$ 30.00	\$ 30.00
2	W/SCREEN SEALANT <i>m</i>	1	PC \$ 40.00	\$ 40.00
3	IU BRKT <i>m</i>	1	PC \$ 26.00	\$ 26.00
4	COOLANT <i>m</i>	1	PC \$ 60.00	\$ 60.00
5	A/C GAS <i>m</i>	1	PC \$ 40.00	\$ 40.00
6	NUMBER PLATE <i>st</i>	1	PC \$ 40.00	\$ 40.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE
27/9/2024
LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: YP6714D
Vehicle Model: CBMQ24090195
Est No:
Claims ref:
Accident Date: 16/09/24
In Charge: BRIAN
Remarks:

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

SPECIAL NET TOTAL S\$

\$ 236.00

LABOUR CHARGE:

- | | | | | |
|---|--|--|--|---------------------|
| 1 | TO CUT / WELD / PANEL BEAT DASH PANEL , REPLACE CABIN BRKT ,SWING ARM.
TO REPLACE DAMAGES ITEMS AND REALIGN ALL THE CONNECTION | | | \$ 1,400.00
1100 |
| 2 | TO SPRAY PAINT ON FRONT PANEL , CORNER PANEL LH/RH, LH A-PILLAR
GRILLE, FRONT BUMPER,DASH PANEL, CHASSIS CROSSMEMBER AND
BOTH FRONT DOOR | | | \$ 1,680.00
1400 |
| 3 | TO REPLACE FRONT WINDSCREEN | | | \$ 150.00
120 |
| 4 | TO ADJUST FOCUS HEADLAMP | | | \$ 80.00
X0 |
| 5 | TO REMOVE /REFIT DASHBOARD AND UPHOSTERY TO FACILITATE REPAIR. | | | \$ 250.00
200? |
| 6 | TO REPLACE A/C SYSTEM , DAMAGES PARTS , VACUUM & REPLENISH A/C GAS | | | \$ 220.00
180 |
| 7 | TO CHECK FOR / RECTIFY WIRING CONNECTION/DIAGNOSIS, RESET
SYSTEM AFTER REPAIR | | | \$ 220.00
120 |

TOTAL LABOUR COST S\$

\$ 4,000.00

AMOUNT S\$ \$ 16,362.75
GST @ 9% \$ 1,472.65
AMOUNT DUE S\$ \$ 17,835.40

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
Hp 90010068
10 days
45
27/09/24
Reason
EXCER: 700
Reg after rep