

ASS. REC. BY:

REF:

C121

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDQ 3446R Yr Regn: 08, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

C.G

1797

Colour

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

171574

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

EGE 20 . 0008423

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Trista

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

18/6/24

D.O.I.

9/7/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fines

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 2/7/2024
VEHICLE : SDQ3446R
MAKE/MODEL : TOYOTA / WISH
CHASSIS NO : ZGE20-0008423
MILLAGE :
TYRE SIZE : 205/60/R16
DOA : 18/06/2024

Not Authorized
C/Simp &
Presurvey After Paint
6days

LIST ITEM

01 PC TAIL GATE
02 PC TAIL GATE ABSORBER @ \$263.88
01 PC TAIL GATE TRIMBOARD
01 PC TAIL GATE OUTER GANISH
01 PC TAIL GATE OUTER HANDLE
01 PC TAIL GATE EMBLEM (LOGO)
01 PC TAIL GATE INNER LOCK
01 PC TAIL GATE CATCH LOCK
01 PC TAIL GATE INNER HANDLE
01 PC REAR BUMPER
02 PC REAR BUMPER SIDE RETAINER @ \$126.89
02 PC REAR BUMPER REFLECTOR @ \$75.58
01 PC REAR END PANEL
01 PC REAR END PANEL TOP GANISH
01 PC REAR WEATHERSTRIP
01 PC REAR LH TAIL LAMP
01 PC REAR LH TAIL LAMP LOWER BRACKET
01 PC REAR LH TAIL GATE LAMP
01 PC REAR LH FENDER
01 PC REAR LH FENDER INNER SHEILD
01 PC FUEL FILLER LID
01 PC FUEL FILLER SHEILD

By \$ 2,179.68 ✓
In \$ 527.76 X
S/P \$ 414.69 X
P/S \$ 407.82 X
S/P \$ 114.45 X
S/P \$ 64.05 ✓
S/P \$ 335.85 X
S/P \$ 117.72 X
S/P \$ 147.15 X
By \$ 2,200.23 ✓
n/s/c/s \$ 253.78 X
n/s/c/s \$ 151.16 X
S \$ 856.70 ?
S/P \$ 325.59 X
S/P \$ 325.59 X
By \$ 904.77 ✓
C/P \$ 132.10 ✓
By \$ 594.69 ✓
By \$ 1,713.57 ✓
S \$ 201.36 ?
S/P \$ 128.85 X
S/P \$ 66.48 X
\$ 12,164.04

Special Nett

02 PC PARKING SENSOR @ \$220
10 PC REAR TRIM BOARD CLIP @ \$8
01 PC REAR WINDSCREEN/GLASS SEALANT
06 PC BUMPER CLIP @ \$8

By \$ 440.00 X
By \$ 80.00 ✓
By \$ 200.00 800.00
By \$ 48.00 ✓
\$ 768.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECTED AREA
3. TO SUPPLY LABOUR TO ALIGN REAR FENDER
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
6. TO SUPPLY DIAGNOSTIC & REPROGRAMMING
7. TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN AND QUARTER GLASS

\$ 1,200.00 900
\$ 900.00 800
\$ 600.00 X
\$ 300.00 200
\$ 200.00 600
\$ 300.00 X
\$ 400.00 1800
\$ 3,900.00

TOTAL PARTS
TOTAL SPECIAL NETT
TOTAL LABOUR
TOTAL COST OF REPAIR

JKK Auto Consultants hence notify

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$ 12,164.04
\$ 768.00
\$ 3,900.00
\$ 16,832.04

Acknowledged by Repairer

Signature:

Date: